

WGS84  
+24ft

40.24377, -104.63368

m  
+6m

1457

T  
±11

SE156



ECMC  
Environmental  
Field Inspection



Aristocrat 11-21 TB  
© 25-Aug-25 12:15:45  
ECMC Environmental Inspection

Signage with emergency contact number is visible.

WGS84  
±23ft

40.24377, -104.63370

Λ<sup>m</sup>  
±6m

1457

△<sup>°T</sup>  
±12

N3




Aristocrat 11-21 TB  
© 25-Aug-25 12:16:04  
ECMC Environmental Inspection

**ECMC**  
**Environmental**  
**Field Inspection**



Looking at the approximate spill location. The excavation at the spill location has been backfilled to a grade above that of the surrounding location.

WGS84 ±22ft 40.24377, -104.63370  $\Delta$  m ±6m 1457 °T ±12 NE35



**ECMC  
Environmental  
Field Inspection** 

Aristocrat 11-21 TB  
© 25-Aug-25 12:16:07  
ECMC Environmental Inspection

Looking at the former facility. The tank battery has been decommissioned. A work-over rig is visible in the background at the adjacent Aristocrat 11-21 well (API # 05-123-15805).

WGS84 40.24366, -104.63370 1454 NE49  
±18ft ±8m

Aristocrat 11-21 TB  
© 25-Aug-25 12:17:18  
ECMC Environmental Inspection



Areas of soil with gray staining are visible on the surface at the backfilled excavation at the approximate spill location.

WGS84 ±12ft 40.24375, -104.63367  $\Delta$   $\frac{m}{\pm 3m}$  1459  $\frac{\circ}{\pm 11}$  NE48



**ECMC**  
**Environmental**  
**Field Inspection**



Aristocrat 11-21 TB  
© 25-Aug-25 12:17:28  
ECMC Environmental Inspection

WGS84 40.24377, -104.63356  $\Delta$  m  $\pm 3m$  1456  $\pm 11$  NE26



**ECMC  
Environmental  
Field Inspection**



Aristocrat 11-21 TB  
© 25-Aug-25 12:17:58  
ECMC Environmental Inspection

Trash (black plastic) is visible across the location.

WGS84 ±10ft 40.24380, -104.63351  $\wedge^m_{\pm 3m}$  1457  $\triangle^{\circ,T}_{\pm 11}$  NW294



**ECMC**  
**Environmental**  
**Field Inspection**



Aristocrat 11-21 TB  
© 25-Aug-25 12:18:27  
ECMC Environmental Inspection

WGS84 40.24364, -104.63353  $\Delta$  m 1456  $\Delta$  T NE30  
 $\pm 18$ ft  $\pm 5$ m  $\pm 1$ ft

**ECMC  
Environmental  
Field Inspection**



Aristocrat 11-21 TB  
© 25-Aug-25 12:19:24  
ECMC Environmental Inspection

WGS84  $\pm 16\text{ft}$  40.24362, -104.63371  $\wedge^m_{\pm 4\text{m}}$  1458  $\triangle^{\circ, T}_{\pm 11}$  NW296



**ECMC**  
**Environmental**  
**Field Inspection**



Aristocrat 11-21 TB  
© 25-Aug-25 12:20:36  
ECMC Environmental Inspection

WGS84  
±12ft

40.24348, -104.63392

±3m

1458

±12

NW313



**ECMC  
Environmental  
Field Inspection**



Aristocrat 11-21 TB  
© 25-Aug-25 12:21:24  
ECMC Environmental Inspection

A pump was observed running at the pond southwest of the spill location.