

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 246-1 Pad

Location #: 324324



Photo # 3717 From entrance to location



Photo # 3718 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 246-1 Pad

Location #: 324324



Aug 25, 2025 at 12:38:47 PM
+39.471896,-108.168500



Aug 25, 2025 at 12:45:02 PM
+39.471856,-108.168794

Photo # 3719 Location

Photo # 3720 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 246-1 Pad

Location #: 324324



Photo # 3721 Location




Photo # 3722 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 246-1 Pad

Location #: 324324



**Photo # 3723 Flowline heating insulation open ended
/wildlife hazard/available for entry by wildlife**



**Photo # 3724 Flowline heating insulation open ended
/wildlife hazard/available for entry by wildlife**

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 246-1 Pad

Location #: 324324



Photo # 3725 Tank lacks required labeling

Photo # 3726 Tank lacks required labeling

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 246-1 Pad

Location #: 324324



Photo # 3727 Tank lacks required labeling



Photo # 3728 Tank lacks required labeling

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 246-1 Pad

Location #: 324324



Photo # 3729 Secondary containment liner needs maintenance



Photo # 3730 Secondary containment liner needs maintenance

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 246-1 Pad

Location #: 324324



Photo # 3731 Holes in liner/liner needs maintenance



Photo # 3732 Barbed wire fence around separator needs maintenance/wildlife hazard

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 246-1 Pad

Location #: 324324



Photo # 3733 Barbed wire fence around separator needs maintenance/wildlife hazard



Photo # 3734 Barbed wire fence around separator needs maintenance/wildlife hazard

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 246-1 Pad

Location #: 324324



Photo # 3735 Stained soils



Photo # 3736 Stained soils

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 246-1 Pad

Location #: 324324



Photo # 3737 Stained soils



Photo # 3738 Stained soils

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 246-1 Pad

Location #: 324324



Photo # 3739 Stained soils



Photo # 3740 Stained soils