

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/05/2025

Submitted Date:

08/20/2025

Document Number:

719700004

FIELD INSPECTION FORM

Loc ID 431674 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 18 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431674	LOCATION	AC			-	Dillard 20M-HZ Pad	AO

General Comment:

*This is an audit of the scout card and related documents followed by a field audit.

Location			
Lease Road:			
	Type Access		
	comment: Adequate		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
	Type BATTERY		
	Comment:		
Corrective Action:			Date:
	Type CONTAINERS		
	Comment: Battery site: Methanol, Motor oil, Coolant, Nitrogen. Placards.		
Corrective Action:			Date:
	Type TANK LABELS/PLACARDS		
	Comment:		
Corrective Action:			Date:
Emergency Contact Number:			
	Comment: Posted.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
	Comment: CORRECTIVE ACTION Item(s): 2.) Overgrown vegetation at Battery site. Refer to Rule 606.c for guidance.		
Corrective Action:	*Remove, manage, & control overgrown vegetation around Battery site. Comply with Rule 606.c. See photo(s) #11.		Date: <u>09/04/2025</u>
Type	OTHER		
	Comment: CORRECTIVE ACTION Item(s): 1.) Stained soil at Compressor(s). Refer to Rules 905.e (Oily Waste) & 608.e (Mechanical Conditions) for guidance. * All Production Facilities, valves, pipes, fittings, and vessels will be securely fastened or sealed, inspected at regular intervals, and maintained in good mechanical condition. All equipment will be engineered, operated, and maintained within the manufacturer's recommended specifications.		
Corrective Action:	** Mitigate stained soil around Compressor(s). Comply with Rules 905.e (Oily Waste) & 608.e (Mechanical Conditions). See photo(s) #7.		Date: <u>09/04/2025</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
	Comment: _____		
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	IGNITOR/COMBUSTOR		
Comment:	Iron pipe.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Separator(s), Compressor(s), VRU(s): Surrounded by metal berms, partial sound wall(s).		
Corrective Action:		Date:	
Equipment:			corrective date
Type: VRU	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:	2: Facility vapor line combustor(s). Controls facility vapors. Pilots: ON.		
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 5		
Comment:	1: Gas Sales, Master; (Phillips 66). Calibration card(s) indicates calibration <= 1 year. Last calibration: 02/26/2025. 3: Gas Sales, Allocation; 1: VRU, Gas Buyback (Chevron). Calibration card(s) indicates calibration <= 1 year. Last calibration: 07/28/2025.		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 9		
Comment:	Battery site: 2: Methanol pump(s), tank(s) w/ drip containment. 1: Nitrogen tank for Instrument Air. 1: Bulk Motor oil tank(s) w/ drip containment. 1: Bulk Coolant tank(s) w/ drip containment. 4: ECD scrubber(s).		
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY			
Comment:	Centralized Battery serves 1 Location ID (431674). (Well(s): 2: Producing PR; 1: Shut-In SI). Centralized Battery serves 1 Tank Battery Facility ID (Pending).					
Corrective Action:					Date:	

Paint						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						

Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	100 BBLs	PBV FIBERGLASS			
Comment:						
Corrective Action:					Date:	

Paint						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						

Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:	Berms shared w/ crude oil, produced H2O tank(s).					
Corrective Action:					Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	9	400 BBLs	STEEL AST		40.565236,-104.572870	
Comment:	Equalizer line(s) connect crude oil tank(s).					
Corrective Action:					Date:	

Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Berms shared w/ crude oil, produced H2O tank(s).				
Corrective Action:				Date:

Wells Served By Facilities Above

AirsID

API Number
123-36727
123-36728
123-36723

API Number	AirsID

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 431674 Type: LOCATION API Number: - Status: AC Insp. Status: AO

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On TUE 08/05/2025 at approximately 15:35 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: PDC ENERGY INC Facility Name: Pending Facility ID: Pending Location Name: Dillard/20M-HZ Pad Location ID: 431674 Well Name(s): See photo(s) #12 attached to this report. API: See "Wells Served By Facilities Above" sec on pg. 5 and/or photo(s) #12 attached to this report. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 2: Producing PR; 1: Shut-In SI. Battery: Active.</p> <p>*CORRECTIVE ACTIONS Item(s): 2.) See "Good Housekeeping" section on page 2 of this report.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	08/20/2025
<p>This is a BATTERY inspection. Well(s): 2: Producing PR; 1: Shut-In SI. Battery: Active.</p> <p>Centralized Battery serves 1 Location ID (431674). (Well(s): 2: Producing PR; 1: Shut-In SI).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p>Reference (Associated Well(s), Battery Inspections): A.) Field Inspection Report doc. #719700002 and/or Location ID #431674 for PR, SI Well(s) info. B.) Field Inspection Report doc. #719700004 and/or Location ID #431674 for Battery / Facility, Equipment info.</p>	evinsb	08/20/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404324618	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7197694
719700005	Inspection photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7197692