

WGS84  
±24ft

40.22748, -104.61350

Λ<sup>m</sup>  
±6m

1482

°T  
±10

NE24



UPRC 13-06J  
© 25-Aug-25 13:03:05  
ECMC Environmental Inspection

**ECMC  
Environmental  
Field Inspection**



Looking at the approximate spill location. The excavation has been backfilled.

WGS84 40.22749, -104.61349  $\Delta$   $\pm 16$ ft  $\Delta$   $\pm 4$ m 1482  $\Delta$   $\pm 12$  SE157



**ECMC**  
**Environmental**  
**Field Inspection**



UPRC 13-06J  
© 25-Aug-25 13:04:37  
ECMC Environmental Inspection  
Pieces of cement were visible in multiple areas of the location.

WGS84  $\pm 12\text{ft}$  40.22744, -104.61354  $\Delta^m$   $\pm 3\text{m}$  1483  $\text{°T}$   $\pm 11$  SE146



**ECMC**  
**Environmental**  
**Field Inspection**



UPRC 13-06J  
© 25-Aug-25 13:05:54  
ECMC Environmental Inspection

WGS84  $\pm 16\text{ft}$  40.22742, -104.61352  $\wedge$  m  $\pm 4\text{m}$  1483  $\nabla$  °T  $\pm 11$  NE67



**ECMC**  
**Environmental**  
**Field Inspection**



UPRC 13-06J  
© 25-Aug-25 13:06:01  
ECMC Environmental Inspection

Pieces of trash or E&P waste (pipe fittings) were visible in multiple areas of the location.

WGS84  $\pm 21\text{ft}$  40.22738, -104.61348  $\pm 3\text{m}$  1483  $\pm 11$  E88



**ECMC  
Environmental  
Field Inspection**



UPRC 13-06J  
© 25-Aug-25 13:06:27  
ECMC Environmental Inspection

WGS84  
±18ft

40.22734, -104.61343

m  
±3m

1482

°T  
±11

SE117



**ECMC  
Environmental  
Field Inspection**



UPRC 13-06J  
© 25-Aug-25 13:06:44  
ECMC Environmental Inspection

WGS84 40.22748, -104.61334  $\Delta$   $\pm 4m$  1482  $\Delta$   $\pm 11$  NE49  
 $\pm 16ft$



**ECMC  
Environmental  
Field Inspection**



UPRC 13-06J  
25-Aug-25 13:07:32  
ECMC Environmental Inspection

WGS84  $\pm 21\text{ft}$  40.22748, -104.61349  $\pm 3\text{m}$  1482  $\pm 11$  NE35



**ECMC**  
**Environmental**  
**Field Inspection**



UPRC 13-06J  
© 25-Aug-25 13:08:30  
ECMC Environmental Inspection