

Inspected Facilities

Facility ID: 288634 Type: WELL API Number: 071-09143 Status: PR Insp. Status: PR

Producing Well

Comment: pr

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
BASED OF PHOTOS SUBMITTED BY OPERATOR IN FIRR DOC #404313273 CA HAS BEEN ADDRESSED SEE ATTACHMENTS FOR OPERATOR PHOTOS.	beardslt	08/27/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716301442	INSP. PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7207655