

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/27/2025

Submitted Date:

08/27/2025

Document Number:

715801448

FIELD INSPECTION FORM

Loc ID 321386 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10459
Name of Operator: EXTRACTION OIL & GAS INC
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 10 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------------|---------------------------------|
| , | | Inspections@civiresources.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 206811 | WELL | SI | 06/01/2025 | GW | 013-06306 | MEMCO MC 8-4 | SI |

General Comment:

[This is a field audit of the scout card, related documents and the location.](#)

Location

Overall Good:

Signs/Marker:

| | | | |
|--|--|-------------------------|--|
| | Type WELLHEAD | | |
| | Comment: Sign not posted | | |
| | Corrective Action: Install sign to comply with Rule 605.d. | Date: <u>09/27/2025</u> | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: [fabricated steel pipe](#)

Corrective Action:

Date:

Type TANK BATTERY

Comment: [fabricated steel pole & wire](#)

Corrective Action:

Date:

Equipment:

corrective date

| | | | | | |
|--|-----|--|--|--|-------|
| Type: Gas Meter Run | # 1 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Type: Emission Control Device | # 1 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Type: Ancillary equipment | # 3 | | | | |
| Comment: automation, telemetry | | | | | |
| Corrective Action: | | | | | Date: |
| Type: Horizontal Heated Separator | # 1 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Type: Bradenhead | # 1 | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Type: Bird Protectors | # 2 | | | | |

| | | |
|--------------------|-----|-------|
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Plunger Lift | # 1 | |
| Comment: | | |
| Corrective Action: | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|---------------------|---------|--------|
| PRODUCED WATER | 1 | <50 BBLs | CONCRETE SUMP/VAULT | | |
| Comment: | | | | | |
| Corrective Action: | | | | | |
| | | | | | Date: |

Paint

| | |
|------------------|--------|
| Condition | |
| Other (Content) | |
| Other (Capacity) | 48 bbl |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|------------------------------------|---------------------|---------------------|-------------|
| Earth | | | | |
| Comment: | shares containment with crude tank | | | |
| Corrective Action: | | | | |
| | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 1 | 300 BBLs | STEEL AST | | 40.072100,-105.149300 |
| Comment: | | | | | |
| Corrective Action: | | | | | |
| | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | | | | |
| Comment: | | | | |
| Corrective Action: | | | | |
| | | | | Date: |

Wells Served By Facilities Above

| |
|------------|
| API Number |
| 013-06305 |
| 013-06306 |

AirsID

| | |
|------------|--------|
| API Number | AirsID |
|------------|--------|

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 206811 Type: WELL API Number: 013-06306 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 10/08/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: in a cellar

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | | Gravel | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

| Comment | User | Date |
|--|--------|------------|
| <p>ECMC Inspection Report Summary On Wednesday 8-27-2025 at approximately 1200 hrs. I, Inspector Robbie Revas, Conducted an audit of the well scout card & related forms followed by an onsite inspection: Operator: Civitas Location # 321386 API # 05-013 Well name: Memco MC 8-4 County: Boulder Weather: Cloudy/light rain Temp: 76* Location: wet While there, I observed a wellsite & tank battery, SI at the time of inspection. During this inspection the following possible compliance issues were observed: 605.d signs: No sign posted, CA date 9-27-2025 Any corrective actions from previous Inspections that have not been addressed are still applicable. See attached photos. A follow up on this site inspection will be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p> | revasr | 08/27/2025 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------|---|
| 715801449 | Location photos | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7208040 |