

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/20/2025

Submitted Date:

08/21/2025

Document Number:

707801785

FIELD INSPECTION FORM

Loc ID 436713 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 17 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
436714	WELL	PR	06/08/2015	GW	045-22361	Valley Farms L 44D-11-06-92	PR
436715	WELL	PR	04/01/2025	GW	045-22362	Valley Farms L 44B-11-06-92	PR
436716	WELL	PR	03/20/2015	GW	045-22363	Valley Farms L 41B-14-06-92	PR
436721	WELL	PR	03/19/2015	GW	045-22367	Valley Farms L 41A-14-06-92	PR
436722	WELL	PR	04/22/2015	GW	045-22368	Valley Farms L 44C-11-06-92	PR
437715	WELL	PR	05/26/2015	GW	045-22439	VALLEY FARMS L 33D-11-06-92	PR
437729	WELL	PR	03/21/2015	GW	045-22443	VALLEY FARMS L 34D-11-06-92	PR
437753	WELL	PR	03/25/2015	GW	045-22446	VALLEY FARMS L 34C-11-06-92	PR
437776	WELL	PR	04/26/2015	GW	045-22449	VALLEY FARMS L 34A-11-06-92	PR
437782	WELL	PR	05/12/2015	GW	045-22450	VALLEY FARMS L 34B-11-06-92	PR

General Comment:

CECMC Inspection Report Summary

On Wednesday 8/20/2025, I, Inspector Scott Ramsey, conducted a routine inspection/audit at TEP Valley farms L, at Location #436713 in Garfield County Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad. No evidence of a tracking pad on location.

During this inspection the following compliance issues were observed:

1. Well signs are illegible.

Refer to photographs of observed compliance issues.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Well signs are illegible.		
Corrective Action:	Provide proper signage.	Date:	09/26/2025

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:

Type	#		corrective date
Type: Plunger Lift	#		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 10		
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 9		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Chemical tank in plastic containment		
Corrective Action:			Date:
Type: Emission Control Device	# 2		
Comment:	1 ECD was running at tme of inspection and was also metered		
Corrective Action:			Date:
Type: Bradenhead	# 10		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 10		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	300 BBLs	HEATED STEEL AST		,
Comment:	3 tanks are not heated				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	436714	Type:	WELL	API Number:	045-22361	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	436715	Type:	WELL	API Number:	045-22362	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	436716	Type:	WELL	API Number:	045-22363	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	436721	Type:	WELL	API Number:	045-22367	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	436722	Type:	WELL	API Number:	045-22368	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	437715	Type:	WELL	API Number:	045-22439	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	437729	Type:	WELL	API Number:	045-22443	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	437753	Type:	WELL	API Number:	045-22446	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Producing Well			
Comment:	Producing		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 437776 Type: WELL API Number: 045-22449 Status: PR Insp. Status: PR

Producing Well			
Comment:	Producing		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 437782 Type: WELL API Number: 045-22450 Status: PR Insp. Status: PR

Producing Well			
Comment:	Producing		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Gravel						
Berms						
		Culverts				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404326231	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7199469
707801792	Photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7199462