

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/19/2025

Submitted Date:

08/21/2025

Document Number:

715202799

**FIELD INSPECTION FORM**

Loc ID 337406 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10699  
Name of Operator: OWN RESOURCES OPERATING LLC  
Address: 305 S RIDGE STREET #6279  
City: BRECKENRIDGE State: CO Zip: 80424

**Findings:**

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat		pat.dolezal@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285627	WELL	PR	05/10/2007	GW	125-10165	HELLING 32-15	PR

**General Comment:**

This is a field audit of the scout card, related documents and the location by SE Compliance Specialist Brian Welsh

**Location**

<b>Lease Road:</b>			
	Type	Access	
	comment:	Two track through pasture	
Corrective Action:			Date:

Overall Good:

<b>Signs/Marker:</b>			
	Type	WELLHEAD	
	Comment:	Lease sign by fence	
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
	Comment:	<input type="text"/>	
	Corrective Action:	<input type="text"/>	Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
	Type	PUMP JACK	
	Comment:	Metal panels around unit, wellhead, VGS and meter shed	
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 2		
	Comment:	Telemetry equipment and gas scrubber	
Corrective Action:			Date:
Type: Prime Mover	# 1		
	Comment:	Kubota gas engine	
Corrective Action:			Date:
Type: Pump Jack	# 1		
	Comment:	Gabel unit	
Corrective Action:			Date:
Type: Vertical Separator	# 1		
	Comment:	Vertical gas separator 50% buried by meter shed	
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
	Comment:	Meter shed on west side of wellhead	
Corrective Action:			Date:

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 285627 Type: WELL API Number: 125-10165 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Casing production. Production reports are up to date at time of inspection](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment: [Access is grassed over. Erosion on access near location](#)

Corrective Action: [Repair erosion and install BMP](#)

Date: 10/19/2025

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404325779	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7199046">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7199046</a>
715202817	location photo	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7199007">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7199007</a>
715202818	Erosion on access	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7199008">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7199008</a>