

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/19/2025

Submitted Date:

08/21/2025

Document Number:

715202800

FIELD INSPECTION FORM

Loc ID 337439 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10699
Name of Operator: OWN RESOURCES OPERATING LLC
Address: 305 S RIDGE STREET #6279
City: BRECKENRIDGE State: CO Zip: 80424

Findings:

- 12 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Dolezal, Pat		pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285814	WELL	PR	05/09/2007	GW	125-10203	HELLING 11-22	PR

General Comment:

This is a field audit of the scout card, related documents and the location by SE Compliance Specialist Brian Welsh

Location			
Lease Road:			
Type	Access		
comment:	Trail through pasture, old homestead and CRP		
Corrective ActionL			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by meter shed		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Rods and tubing laying on north side of pupming unit outside of the fence		
Corrective Action:	Comply with rule 606		Date: 09/19/2025
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Metal panels around unit, wellhead, VGS and meter shed		
Corrective Action:			Date:
Equipment:			
Type: Vertical Separator	# 1		corrective date
Comment:	Vertical gas separator 50% buried by meter shed		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Telemetry equipment and electric panel		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Meter run on south side of wellhead		

Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Gabel unit		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 285814 Type: WELL API Number: 125-10203 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Production reports are up to date at time of inspection](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: [Erosion leading off of location to the west needs repaired and BMP installed](#)

Corrective Action: [Repair erosion and install stormwater BMPs](#)

Date: 09/19/2025

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404325780	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7199047
715202814	location photo	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7199009
715202815	Rods and tubing on location	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7199010
715202816	erosion on west side of location	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7199011