

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/22/2025

Submitted Date:

08/22/2025

Document Number:

717900291

FIELD INSPECTION FORM

Loc ID 448255 Inspector Name: Robinson, Taylor On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 7 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	All Inspections

General Comment:

This is an environmental inspection for Spill ID 484984 Walters Pad. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

Comment: Weeds/trash observed on location.

Corrective Action: Comply with Rule 606.c.

Date: 09/05/2025

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

This inspection was in response to Rem Project No. 31720 which is an ongoing remediation. Various samples were not run for full Table 915-1 list of constituents. Inspector conducted AVO inspections at the site to confirm the presence or absence of any residual hydrocarbons were left on site. None were observed. This is an active facility.

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Location Construction

Location ID: 448255 CDP: _____

Comment:

Corrective Action:

Date: _____

Form 2A COAs:

Comment:

Corrective Action:

Date: _____

Wildlife BMPs:

Comment:

Corrective Action:

Date: _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Comments: Erosion BMPs: Unlined, unlabeled, and an enclosed soil stock pile on site. Potential E&P waste stockpiled on location without adequate BMPs.

Other BMPs:

Corrective Action: Comply with 905.e. and 913.b.(5)B and 913.b.(5)B i-v Guidance Date: 09/05/2025

5

Comment: Rills observed throughout the perimeter of the location. Offsite runoff needs to be pulled back and rills filled and graded. Missing/inadequate BMPs to control stormwater runoff.

Corrective Action: Comply with 1002.f.(2).

Date: 09/05/2025

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment:

Corrective Action: Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

ECMC Comments

Comment	User	Date
<p>This inspection was in response to Rem Project No. 31720 which is an ongoing remediation. Various samples were not run for full Table915-1 list of constituents. Inspector conducted AVO inspections at the site to confirm the presence or absence of any residual hydrocarbons were left on site. None were observed.</p> <p>This is an active facility.</p> <p>Rills present. Stock pile present with no erosion control BMPs.</p>	robinsotl	08/22/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404327707	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7201482
717900292	photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7201478