

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/05/2025

Submitted Date:

08/22/2025

Document Number:

719700008

**FIELD INSPECTION FORM**

Loc ID 427337 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 69175  
Name of Operator: PDC ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 17 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@chevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
427337	LOCATION	AC			-	Dillard 20Y-HZ Pad	IO

**General Comment:**

\*This is an audit of the scout card and related documents followed by a field audit.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Battery site: Methanol, Motor oil, Coolant, Nitrogen. Placards.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Posted		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	CORRECTIVE ACTION Item(s): 1.) Overgrown vegetation at Battery site. Refer to Rule 606.c for guidance.		
Corrective Action:	*Remove, manage, & control overgrown vegetation around Battery site. Comply with Rule 606.c. See photo(s) #8.		Date: <u>09/05/2025</u>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	IGNITOR/COMBUSTOR		
Comment:	Iron panel.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Separator(s), Compressor(s): Surrounded by metal berms.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 5		
Comment:	Battery site: 1: Nitrogen tank for Instrument Air. 4: ECD scrubber(s).		
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 2		
Comment:	2: Facility vapor line combustor(s). Controls facility vapors. Pilots: OFF. Shut-down.		
Corrective Action:			Date:
Type: Gas Meter Run	# 4		
Comment:	1: Gas Sales, Master; (Phillips 66). Calibration card(s) indicates calibration <= 1 year. Last calibration: 02/26/2025. 3: Gas Sales, Allocation; 1: VRU, Gas Buyback (Chevron). Calibration card(s) indicates calibration <= 1 year. Last calibration: 01/16/2025.		
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY			
Comment:	Centralized Battery serves 1 Location ID (427337). (Well(s): 3: Temporarily Abandoned   TA). Centralized Battery serves 1 Tank Battery Facility ID (Pending).					
Corrective Action:						Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	100 BBLs	PBV FIBERGLASS		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Berms shared w/ crude oil, produced H2O tank(s).				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	10	400 BBLs	STEEL AST		40.552137,-104.564513
Comment: Equalizer line(s) connect 6 of 10 crude oil tank(s).					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Berms shared w/ crude oil, produced H2O tank(s).				
Corrective Action:				Date:

**Wells Served By Facilities Above**

API Number
123-36601
123-36600
123-36602

**AirsID**

API Number	AirsID
------------	--------

**Venting:**

Yes/No	NO
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 427337 Type: LOCATION API Number: - Status: AC Insp. Status: IO

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On TUE 08/05/2025 at approximately 16:49 hrs. I, Bret Evins, conducted an onsite inspection at:                      Operator Name: PDC ENERGY INC                      Facility Name: Pending                      Facility ID: Pending                      Location Name: Dillard/20Y-HZ Pad                      Location ID: 427337                      Well Name(s):                      See photo(s) #8 attached to this report.                      API:                      See "Wells Served By Facilities Above" sec on pg. 4 and/or photo(s) #8 attached to this report.                      Location County: Weld County, Colorado                      Weather: Partly Sunny, dry.</p> <p>While there, I observed:                      Well(s): 3: Temporarily Abandoned   TA.                      Battery: Inactive   Shut-down.</p> <p>*CORRECTIVE ACTIONS Item(s):                      1.) See "Good Housekeeping" section on page 2 of this report.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	08/22/2025
<p>This is a BATTERY inspection.                      Well(s): 3: Temporarily Abandoned   TA.                      Battery: Inactive   Shut-down.</p> <p>Centralized Battery serves 1 Location ID (427337).                      (Well(s): 3: Temporarily Abandoned   TA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p>Reference (Associated Well(s), Battery Inspections):                      A.) Field Inspection Report doc. #719700006 and/or Location ID #427337 for TA Well(s) info.                      B.) Field Inspection Report doc. #719700008 and/or Location ID #427337 for Battery / Facility, Equipment info.</p>	evinsb	08/22/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404327493	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7201210">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7201210</a>
719700010	Inspection photo(s)	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7201209">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7201209</a>