

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
08/13/2025
Submitted Date:
08/22/2025
Document Number:
719700013

FIELD INSPECTION FORM

Loc ID 330074 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
19 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
330074	LOCATION	AC			-	HSR-HOBE STATE-63N62W 32NWNE	IO

General Comment:
**This is an audit of the scout card and related documents followed by a field audit.*

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Posted.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	CORRECTIVE ACTION Item(s): 1.) Overgrown vegetation at Battery site. Refer to Rule 606.c for guidance.		
Corrective Action:	*Remove, manage, & control overgrown vegetation around Battery site. Comply with Rule 606.c. See photo(s) #3, 4.		Date: <u>09/02/2025</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	IGNITOR/COMBUSTOR		
Comment:	Barbed wire.		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Barbed wire.		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Barbed wire.		
Corrective Action:			Date:

Equipment:		corrective date
Type: Horizontal Heated Separator	# 2	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 3	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 2	
Comment:	2: Gas Sales, Master; (Phillips 66). Calibration card(s) indicates calibration <= 1 year. Last calibration: 01/29/2025. Disconnected.	
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment:	1: Crude storage vapor line combustor(s). Controls crude oil tank(s) vapors. Pilots: OFF Shut-down.	
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	Battery site: 1: ECD scrubber(s).	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Centralized Battery serves 1 Location IDs (330074). (Well(s): 1: Shut-In SI). Centralized Battery serves 1 Tank Battery Facility ID (Pending). Battery also serves HSR-Lost Creek 1-32. (Did NOT include Loc # for this inspection.)				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV FIBERGLASS		,
Comment:	Open top w/ iron frame, wire mesh cover.				
Corrective Action:					Date:

<u>Paint</u>	
Condition	
Other (Content)	
Other (Capacity)	75 Bbls.
Other (Type)	

<u>Berms</u>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment: Open top w/ iron frame, wire mesh cover.				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		
Comment: Open top w/ iron frame, wire mesh cover.					
Corrective Action:					Date:

<u>Paint</u>	
Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

<u>Berms</u>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment: Berms shared w/ crude oil, produced H2O tank(s).				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		40.187540,-104.346110
Comment:					
Corrective Action:					Date:

<u>Paint</u>	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

<u>Berms</u>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment: Berms shared w/ crude oil, produced H2O tank(s).				
Corrective Action:				Date:

AirsID

API Number	AirsID
------------	--------

Wells Served By Facilities Above

API Number

123-19589

123-18355

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 330074 Type: LOCATION API Number: - Status: AC Insp. Status: IO

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Comment: <input style="width: 90%;" type="text"/> Corrective Action: <input style="width: 90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments		
Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On WED 08/13/2025 at approximately 15:32 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: KP KAUFFMAN COMPANY INC Facility Name: Pending Facility ID: Pending Location Name: HSR-HOBE STATE-63N62W/32NWNE Location ID: 330074 Well Name(s): See photo(s) #6 attached to this report. API: See "Wells Served By Facilities Above" sec on pg. 5 and/or photo(s) #6 attached to this report. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Shut-In SI. Battery: Inactive Shut-down.</p> <p>*CORRECTIVE ACTIONS Item(s): 1.) See "Good Housekeeping" section on page 2 of this report.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	08/22/2025
<p>This is a BATTERY inspection. Well(s): 1: Shut-In SI. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 1 Location IDs (330074). (Well(s): 1: Shut-In SI).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p>Reference (Associated Well(s), Battery Inspections): A.) Field Inspection Report doc. #719700011 and/or Location ID #330074 for SI Well(s) info. B.) Field Inspection Report doc. #719700013 and/or Location ID #330074 for Battery / Facility, Equipment info.</p>	evinsb	08/22/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404327824	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7201625
719700015	Inspection photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7201624