

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/28/2025

Submitted Date:

08/28/2025

Document Number:

719000522

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
325755 _____ GARCIA, CHARLES _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96735
Name of Operator: WILLIFORD RESOURCES LLC
Address: 6506 S LEWIS AVE STE 102
City: TULSA State: OK Zip: 74136

Findings:

- 8 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
		hwilli@swbell.net	
		glennstevens95@gmail.com	
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215338	WELL	SI	02/01/2025	OW	067-06943	FIELDS 1	SI

General Comment:

Inspection Report Summary
On 8/28/25 | Inspector Charles Garcia
conducted an on-site inspection.
Location: FIELDS 1
Operator: WILLIFORD RESOURCES
API#: 067-06943
County: LaPlata

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	LOCATION SIGN		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	918-712-8828 911 EMERGENCY		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	CATTLE PANELS		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	CATTLE PANELS		
Corrective Action:			Date:
Equipment:			
Type: Pump Jack			# 1
Comment:			
Corrective Action:			Date:
Type: Bradenhead			# 1
Comment:			
Corrective Action:			Date:
Type: Prime Mover			# 1
Comment:			GAS
Corrective Action:			Date:
Type: Vertical Heated Separator			# 0
Comment:			
Corrective Action:			Date:
Type: Other			# 1
Comment:			WELLHEAD
Corrective Action:			Date:
Venting:			

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 215338 Type: WELL API Number: 067-06943 Status: SI Insp. Status: SI

Producing Well

Comment: WELL WAS RUNING WHEN I ARRIVED TO LOCATION HOW EVER SHOWING SHUT IN STATUS SEE LOCATION VIDEO

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/23/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000523	LOCATION PICTURES	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7211458
719000524	LOCATION VIDEO	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7211459