

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/13/2025

Submitted Date:

08/23/2025

Document Number:

719700016

FIELD INSPECTION FORM

Loc ID 332212 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 65110
Name of Operator: O'BRIEN ENERGY RESOURCES CORP
Address: 18 CONGRESS ST STE 207
City: PORTSMOUTH State: NH Zip: 03801

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|--------------|--------------------------------|---------------------------------|
| Icke, Dean | 303-249-2436 | Hdpumpingservicesllc@gmail.com | |
| Forma, Joe | 603-944-8253 | joeforma@obenergy.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 270985 | WELL | PR | 12/01/2021 | GW | 123-21976 | SOUTH LOST CREEK 8 | PR |

General Comment:

*This is an audit of the scout card and related documents followed by a field audit.

Location

| | | | |
|--------------------|----------|--|-------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Adequate | | |
| Corrective Action: | | | Date: |

Overall Good:

| | | | |
|----------------------|----------|--|-------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|----------------------------------|---------|--|-------------|
| Emergency Contact Number: | | | |
| Comment: | Posted. | | |
| Corrective Action: | | | Date: _____ |

| | | | |
|---------------------------|-----------------------------------------------------------------------------------------------------------------|--|-------------------------|
| Good Housekeeping: | | | |
| Type | WEEDS | | |
| Comment: | CORRECTIVE ACTION Item(s): 1.) Overgrown vegetation at wellsite. Refer to Rule 606.c for guidance. | | |
| Corrective Action: | *Remove, manage, & control overgrown vegetation around wellsite. Comply with Rule 606.c. See photo(s) #1. | | Date: <u>09/02/2025</u> |

Overall Good:

| | | | |
|--------------------------------------------------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: _____ | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |

| | | | |
|--------------------|-------------|--|-------|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Iron panel. | | |
| Corrective Action: | | | Date: |

| | | | |
|--------------------|-----------------------------|--|-----------------|
| Equipment: | | | corrective date |
| Type: Bradenhead | # 1 | | |
| Comment: | Appears plumbed to surface. | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| Tanks and Berms: | | | | | |
|-------------------------|---|----------|---------------------|---------|-----------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| | | | CENTRALIZED BATTERY | | 40.191800,-104.336800 |

| | | | |
|--------------------|---------------------------------------------------------------------------------------------------------------------------------------------------|-------|--|
| Comment: | Centralized Battery serves 1 Location IDs (332212). (Well(s): 1: Producing PR). Centralized Battery serves 1 Tank Battery Facility ID (Pending). | | |
| Corrective Action: | | Date: | |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 270985 Type: WELL API Number: 123-21976 Status: PR Insp. Status: PR

Producing Well

Comment: Producing| PR.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/21/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

| Reclamation - Storm Water - Pit | | | | | | |
|----------------------------------------------------------------------------------------------------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|-------------|
| Storm Water: | | | | | | |
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Gravel | Pass | Gravel | Pass | | | |
| Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/> | | | | | | Date: _____ |
| Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT | | | | | | |

| ECMC Comments |
|---------------|
|---------------|

| Comment | User | Date |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|------------|
| <p>CECMC Inspection Report Synopsis:</p> <p>On WED 08/13/2025 at approximately 15:57 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: O'BRIEN ENERGY RESOURCES CORP Location Name: SOUTH LOST CREEK-63N62W/28SWSW Location ID: 332212 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1:Producing PR. Battery: Inactive Shut-down.</p> <p>*CORRECTIVE ACTIONS Item(s): 1.) See "Good Housekeeping" section on page 2 of this report.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p> | evinsb | 08/23/2025 |
| <p>This is a WELL inspection. Well(s): 1: Producing PR. Battery: Active.</p> <p>Centralized Battery serves 1 Location IDs (332212). (Well(s): 1: Producing PR).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p>Reference (Associated Well(s), Battery Inspections): A.) Field Inspection Report doc. #719700016 and/or Location ID #332212 for PR Well(s) info. B.) Field Inspection Report doc. #719700018 and/or Location ID #332212 for Battery / Facility, Equipment info.</p> | evinsb | 08/23/2025 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 404327890 | INSPECTION SUBMITTED | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7201991 |
| 719700017 | Inspection photo(s) | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7201987 |