

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/13/2025

Submitted Date:

08/23/2025

Document Number:

719700022

**FIELD INSPECTION FORM**

Loc ID 306102 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 65110  
Name of Operator: O'BRIEN ENERGY RESOURCES CORP  
Address: 18 CONGRESS ST STE 207  
City: PORTSMOUTH State: NH Zip: 03801

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 13 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Icke, Dean	303-249-2436	Hdpumpingservicesllc@gmail.com	
Forma, Joe	603-944-8253	joeforma@obenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
306102	LOCATION	AC			-	LOST CREEK-63N62W 16NESE	IO

**General Comment:**

\*This is an audit of the scout card and related documents followed by a field audit.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Posted.		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	CORRECTIVE ACTION Item(s): 1.) Overgrown vegetation at Battery site. Refer to Rule 606.c for guidance.		
Corrective Action:	*Remove, manage, & control overgrown vegetation around Battery site. Comply with Rule 606.c. See photo(s) #1, 3, 4, 5.		Date: <u>09/02/2025</u>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Barbed wire.		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Barbed wire. Surrounded by earth berms.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type:	Horizontal Heated Separator	# 1	corrective date
Comment:			
Corrective Action:			Date:

Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:	1: Gas Sales, Master; (Phillips 66). Calibration card(s) indicates calibration > 1 year. Last calibration: 03/17/2017. Inactive. 1: Gas meter: REMOVED. Meter run remains on site.		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Centralized Battery serves 1 Location IDs (306102). (Well(s): 1: Temporarily Abandoned   TA). Centralized Battery serves 1 Tank Battery Facility ID (Pending).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV STEEL		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Berms shared w/ crude oil, produced H2O tank(s).				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS

CRUDE OIL	1	300 BBLs	STEEL AST		40.223872,-104.321660
-----------	---	----------	-----------	--	-----------------------

Comment:	
Corrective Action:	Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Berms shared w/ crude oil, produced H2O tank(s).				
Corrective Action:				Date:

**Wells Served By Facilities Above**

**AirsID**

API Number
123-23992

API Number	AirsID
------------	--------

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 306102 Type: LOCATION API Number: - Status: AC Insp. Status: IO

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit						
<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Comment: <input style="width: 90%;" type="text"/> Corrective Action: <input style="width: 90%;" type="text"/>						Date: _____
<b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments		
Comment	User	Date
<p><a href="#">CECMC Inspection Report Synopsis:</a></p> <p>On WED 08/13/2025 at approximately 17:10 hrs. I, Bret Evins, conducted an onsite inspection at:                      Operator Name: O'BRIEN ENERGY RESOURCES CORP                      Facility Name: Pending                      Facility ID: Pending                      Location Name: LOST CREEK-63N62W/16NESE                      Location ID: 306102                      Well Name(s):                      See photo(s) #6 attached to this report.                      API:                      See "Wells Served By Facilities Above" sec on pg. 4 and/or photo(s) #6 attached to this report.                      Location County: Weld County, Colorado                      Weather: Mostly Sunny, dry.</p> <p>While there, I observed:                      Well(s): 1: Temporarily Abandoned   TA.                      Battery: Inactive   Shut-down.</p> <p>*CORRECTIVE ACTIONS Item(s):                      1.) See "Good Housekeeping" section on page 2 of this report.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	08/23/2025
<p>This is a BATTERY inspection.                      Well(s): 1: Temporarily Abandoned   TA.                      Battery: Inactive   Shut-down.</p> <p>Centralized Battery serves 1 Location IDs (306102).                      (Well(s): 1: Temporarily Abandoned   TA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p>Reference (Associated Well(s), Battery Inspections):                      A.) Field Inspection Report doc. #719700020 and/or Location ID #306102 for TA Well(s) info.                      B.) Field Inspection Report doc. #719700022 and/or Location ID #306102 for Battery / Facility, Equipment info.</p>	evinsb	08/23/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404327893	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7201994">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7201994</a>
719700023	Inspection photo(s)	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7201990">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7201990</a>