

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 216-25 Pad

Location #: 324202



Photo # 3452 From entrance to location

Photo # 3453 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 216-25 Pad

Location #: 324202



Photo # 3454 Location



Photo # 3455 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 216-25 Pad

Location #: 324202



Photo # 3456 Location



Photo # 3457 Fencing needs maintenance/wildlife hazard

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 216-25 Pad

Location #: 324202



Photo # 3458 Fencing needs maintenance/wildlife hazard



Photo # 3459 Fencing needs maintenance/wildlife hazard

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 216-25 Pad

Location #: 324202



Photo # 3460 Fencing needs maintenance/wildlife hazard



Photo # 3461 Debris

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 216-25 Pad

Location #: 324202



Photo # 3462 Unmarked deadman



Photo # 3463 Same unmarked deadman

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 216-25 Pad

Location #: 324202



Photo # 3464 Open ended piping near wellhead/wildlife hazard



Photo # 3465 Open ended piping near wellhead/wildlife hazard

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 216-25 Pad

Location #: 324202



Aug 25, 2025 at 11:12:46 AM
+39.491967,-108.176431



Aug 25, 2025 at 11:12:09 AM
+39.491967,-108.176431

Photo # 3466 PUCKETT 216-25 Bradenhead line tied into flowline/no FORM 4 SUNDRY – Additionally the line lacks a check valve

Photo # 3467 PUCKETT 216-25 Bradenhead line tied into flowline/no FORM 4 SUNDRY – Additionally the line lacks a check valve

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 216-25 Pad

Location #: 324202



Photo # 3468 Debris