

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/27/2025

Submitted Date:

08/30/2025

Document Number:

708907335

**FIELD INSPECTION FORM**

Loc ID 335820 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10844  
Name of Operator: QB ENERGY OPERATING LLC  
Address: 1001 17TH STREET SUITE 1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 26 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
QB ENERGY		ecmc.inspections@qb-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278556	WELL	PR	05/01/2024	GW	045-10897	CHEVRON 6-43D	PR
278557	WELL	PR	05/01/2024	GW	045-10896	CHEVRON 6-44D	PR
280172	WELL	SI	02/01/2025	GW	045-11211	CHEVRON 6-442D	SI

**General Comment:**

This is a Field Inspection/Audit of the scout card, related documents and the location.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Tank labels have previous operators name - please refer to photo log		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:	911/970-285-2615		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No \_\_\_\_\_

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:
Type	OTHER		
Comment:	Liquid nitrogen tank - pipe rail fence		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Other	# 1		
Comment:	Open ended flowline/wildlife hazard/unused flowline lacks OOSLAT		
Corrective Action:	Comply with CECMC Rules 602 & 1101	Date:	09/06/2025
Type: Bradenhead	# 3		
Comment:	No form of pressure monitoring equipment located on bradenheads, bradenhead valves are accessible		
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		
Comment:	Marked		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Liquid nitrogen tank		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		,
Comment:	Tank not equipped with telemetry				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent			
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 278556 Type: WELL API Number: 045-10897 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing, well on plunger lift

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 278557 Type: WELL API Number: 045-10896 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing, well on plunger lift

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 280172 Type: WELL API Number: 045-11211 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Shut In  
Last produced December 2024

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						Small amount of light compaction
		Ditches				
		Compaction				Small amount of light compaction
		Rip Rap				
				Material Handling And Spill Prevention		Chemical tank containment
Other						Soil stockpile with dirt berm BMP
Other	Fail					Stockpiled soils lack BMP's
		Sediment Traps				
		Gravel				Sparse to none
Berms						
		Culverts				
Gravel						Sparse to none in most areas

Comment: [2 soil stockpiles on location -](#)

[1 stockpile has a dirt berm BMP](#)

[2nd stockpile lacks BMP's](#)

Corrective Action: [Comply with CECMC Rule 1002](#)

Date: 09/14/2025

**Pits:**  NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary                      On 08/27/2025 at approximately 14:27 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection/audit at QB ENERGY OPERATING LLC CHEVRON H07A 696 Pad                      Location # 335820 in Garfield County Colorado.                      Please refer to inspection/audit 707801230 conducted on 11/15/2024, previous corrective actions have been completed.                      Location is within High Priority/Density/NSO/Black Bear Habitat areas.                      Location is approximately 88 yards from Garden Gulch.                      Location is in close proximity to 3 drainages that contribute to Garden Gulch.                      While there, I observed normal production operations.</p> <p>During this inspection/audit the following compliance issues were observed:</p> <ol style="list-style-type: none"> <li>1. Equipment - Open ended flowline/wildlife hazard/unused flowline lacks OOSLAT - Comply with rules 602 &amp; 1101 with a CA date of 09/06/2025</li> <li>2. Stormwater - Stockpiled soils lack BMP's - Comply with rule 1002 with a CA date of 09/14/2025</li> </ol> <p>A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.                      This is a summary of inspection/audit report.</p> <p>Any corrective actions from previous inspections/audits that have not been addressed are still applicable.</p>	smelserw	08/30/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708907337	Inspection/Audit 708907335 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7212991">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7212991</a>
708907338	Inspection/Audit 708907335 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7212992">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7212992</a>