

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
08/13/2025
Submitted Date:
08/24/2025
Document Number:
719700024

FIELD INSPECTION FORM

Loc ID 305139 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 65110
Name of Operator: O'BRIEN ENERGY RESOURCES CORP
Address: 18 CONGRESS ST STE 207
City: PORTSMOUTH State: NH Zip: 03801

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 14 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Forma, Joe	603-944-8253	joeforma@obenergy.com	All Inspections
Icke, Dean	303-249-2436	Hdpumpingservicesllc@gmail.com	
		dnr_ecmc_engineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274598	WELL	PR	04/01/2022	OW	123-22545	LOST CREEK DEVELOPMENT 23	SI

General Comment:

*This is an audit of the scout card and related documents followed by a field audit.

Location			
Lease Road:			
	Type	Access	
	comment:	Adequate	
	Corrective ActionL		Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
	Type	WELLHEAD	
	Comment:		
	Corrective Action:		Date:
Emergency Contact Number:			
	Comment:	Posted.	
	Corrective Action:		Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	CORRECTIVE ACTION Item(s): 1.) Stained soil at wellsite(s). Refer to Rules 905.e (Oily Waste) & 608.e (Mechanical Conditions) for guidance. * All Production Facilities, valves, pipes, fittings, and vessels will be securely fastened or sealed, inspected at regular intervals, and maintained in good mechanical condition. All equipment will be engineered, operated, and maintained within the manufacturer??s recommended specifications.		
Corrective Action:	** Mitigate stained soil around wellsite(s). Comply with Rules 905.e (Oily Waste) & 608.e (Mechanical Conditions). See photo(s) #1, 3.		Date: <u>09/02/2025</u>
Type	TRASH		
Comment:	CORRECTIVE ACTION Item(s): 2.) Trash at wellsite(s). Refer to Rule 606.d for guidance.		
Corrective Action:	*Remove trash around wellsite. Plastic tank, used grease tube(s), bent scrubber tank. Comply with Rule 606.d. See photo(s) #1, 2, 3.		Date: <u>09/02/2025</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
	Comment: _____		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	CORRECTIVE ACTION Item(s): 3.) Pumpjack safety fencing NOT installed. Refer to Rule 602.c, GENERAL SAFTEY REQUIREMENTS. Operators are responsible for ensuring that operations are conducted with due regard for the safety of employees, for the preservation and conservation of property, and for protecting and minimizing adverse impacts to public health, safety, welfare, the environment, and wildlife resources.		
Corrective Action:	*Install pumpjack safety fencing. Comply with Rule 602.c. See photo(s) #1, 2.		Date: <u>09/02/2025</u>

Type	LOCATION		
Comment:	Barbed wire.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas engine drives pump jack. Inactive. Shut-down.		
Corrective Action:		Date:	

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.241459,-104.335132
Comment:	Centralized Battery serves 1 Location IDs (305139). (Well(s): 1: Shut-In SI). Centralized Battery serves 1 Tank Battery Facility ID (Pending).				
Corrective Action:				Date:	

Paint					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	

Venting:					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	

Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities

Facility ID: 274598 Type: WELL API Number: 123-22545 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Shut-in.
Pumpjack: Inactive. Shut-down

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 10/21/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments		
Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On WED 08/13/2025 at approximately 17:44 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: O'BRIEN ENERGY RESOURCES CORP Location Name: LOST CREEK DEVELOPMENT-63N62W/9SWNW Location ID: 305139 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Partly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Shut-In SI Battery: Inactive Shut-down.</p> <p>*CORRECTIVE ACTIONS Item(s): 2.) See "Good Housekeeping" section on page 2 of this report. 1.) See "Fencing" section on page 2 of this report.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	08/24/2025
<p>This is a WELL inspection. Well(s): 1: Shut-In SI. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 1 Location IDs (305139). (Well(s): 1: Shut-In SI).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p>Reference (Associated Well(s), Battery Inspections): A.) Field Inspection Report doc. #719700024 and/or Location ID #305139 for SI Well(s) info. B.) Field Inspection Report doc. #719700026 and/or Location ID #305139 for Battery / Facility, Equipment info.</p>	evinsb	08/24/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404328059	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7202521
719700025	Inspection photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7202519