

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/13/2025

Submitted Date:

08/24/2025

Document Number:

719700026

FIELD INSPECTION FORM

Loc ID 305139 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 65110
Name of Operator: O'BRIEN ENERGY RESOURCES CORP
Address: 18 CONGRESS ST STE 207
City: PORTSMOUTH State: NH Zip: 03801

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 12 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Forma, Joe	603-944-8253	joeforma@obenergy.com	All Inspections
Icke, Dean	303-249-2436	Hdpumpingservicesllc@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
305139	LOCATION	AC			-	LOST CREEK DEVELOPMENT-63N62W 9SWNW	IO

General Comment:

*This is an audit of the scout card and related documents followed by a field audit.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Posted.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	CORRECTIVE ACTION Item(s): 1.) Overgrown vegetation at Battery site. Refer to Rule 606.c for guidance.		
Corrective Action:	*Remove, manage, & control overgrown vegetation around Battery site. Comply with Rule 606.c. See photo(s) #1, 3, 4, 5.		Date: <u>09/02/2025</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:	Surrounded by earth berms.		
Corrective Action:			Date:
Type	LOCATION		
Comment:	Barbed wire.		
Corrective Action:			Date:
Equipment:			
Type:	Horizontal Heated Separator	# 1	corrective date
Comment:			
Corrective Action:			Date:

Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Comment: Centralized Battery serves 1 Location IDs (305139). (Well(s): 1: Shut-In SI). Centralized Battery serves 1 Tank Battery Facility ID (Pending).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.241459,-104.335132
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Berms shared w/ crude oil, produced H2O tank(s).			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
-----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Berms shared w/ crude oil, produced H2O tank(s).					
Corrective Action:				Date:	

Wells Served By Facilities Above

AirsID

API Number	API Number	AirsID
123-22545		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 305139 Type: LOCATION API Number: - Status: AC Insp. Status: IO

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Comment: <input style="width: 90%;" type="text"/> Corrective Action: <input style="width: 90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments		
Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On WED 08/13/2025 at approximately 17:54 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: O'BRIEN ENERGY RESOURCES CORP Facility Name: Pending Facility ID: Pending Location Name: LOST CREEK DEVELOPMENT-63N62W/9SWNW Location ID: 305139 Well Name(s): See photo(s) #6 attached to this report. API: See "Wells Served By Facilities Above" sec on pg. 4 and/or photo(s) #6 attached to this report. Location County: Weld County, Colorado Weather: Partly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Shut-In SI Battery: Inactive Shut-down.</p> <p>*CORRECTIVE ACTIONS Item(s): 1.) See "Good Housekeeping" section on page 2 of this report.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	08/24/2025
<p>This is a BATTERY inspection. Well(s): 1: Shut-In SI. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 1 Location IDs (305139). (Well(s): 1: Shut-In SI).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p>Reference (Associated Well(s), Battery Inspections): A.) Field Inspection Report doc. #719700024 and/or Location ID #305139 for SI Well(s) info. B.) Field Inspection Report doc. #719700026 and/or Location ID #305139 for Battery / Facility, Equipment info.</p>	evinsb	08/24/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404328060	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7202522
719700027	Inspection photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7202520