

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/26/2025

Submitted Date:

08/26/2025

Document Number:

699507433

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
320080 _____ MEDINA, JUSTIN _____ 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10695
Name of Operator: BEHRENS RESOURCES INC
Address: PO BOX 188
City: DEER TRAIL State: CO Zip: 80135

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Hickey, Mike		michael.hickey@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202552	WELL	SI	03/31/2014	GW	001-07957	FARM RANCH EXPLORATION 6 (OWP)	SI

General Comment:

OWP inspection

Inspected Facilities

Facility ID: 202552 Type: WELL API Number: 001-07957 Status: SI Insp. Status: SI

Workover

Comment: OWP inspection.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<u>This is an OPW inspection. At time of inspection Tool Pusher informed me that they had just set cement plug, and were in process of TOH, and run back in with new BHA.</u>	medinaj	08/26/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699507434	inspection photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7213321