

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/24/2025

Submitted Date:

08/31/2025

Document Number:

708907342

FIELD INSPECTION FORM

Loc ID 383295 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 20 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
QB ENERGY		ecmc.inspections@qb-energy.com	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
Katz, Aaron		aaron.katz@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274782	WELL	SI	02/01/2025	GW	045-13392	PUCKETT 11B-25	SI

General Comment:

[This is a Field Inspection/Audit of the scout card, related documents and the location.](#)

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/970-285-2615		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Loose barbed wire in the interim area/wildlife & personnel hazard - refer to photo log Please refer to Fencing for CA		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:	Barbed wire fence		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Piperail fence		

Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbed wire fence Fencing needs maintenance/wildlife hazard Additionally there is loose barbed wire in the interim area/wildlife & personnel hazard		
Corrective Action:	Comply with CECMC Rule 602	Date:	09/07/2025

Equipment:			corrective date
Type: Other	# 1		
Comment:	Open ended piping near wellhead/wildlife hazard		
Corrective Action:	Comply with CECMC Rule 602	Date:	09/07/2025
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Meter calibration info not conspicuously posted		
Corrective Action:	Comply with CECMC Rule 430	Date:	09/10/2025

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		,
Comment:	Tank equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 274782 Type: WELL API Number: 045-13392 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Shut In
Last produced December 2024
Well lacks wellbore diagram/not in compliance with CECMC Rule 420

Corrective Action: Comply with CECMC Rule 420 & submit wellbore diagram via FORM 4 SUNDRY or FORM 17 Date: 09/30/2025

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Sediment Traps				
		Drains				
		Culverts				
Berms						
Gravel						Sparse to none in most areas
		Compaction				Small amount of light compaction
		Ditches				
		Rip Rap				
		Check Dams				
		Gravel				Sparse to none
Compaction						Light compaction in some areas
		Berms				
Other	Fail					Failure to minimize erosion & sediment transport

Comment: 1. Failure to minimize erosion & transport of sediment off location/insufficient BMP's

Corrective Action: Comply with CECMC Rule 1002

Date: 09/15/2025

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary On 08/24/2025 at approximately 14:13 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection/audit at QB ENERGY OPERATING LLC PUCKETT 11B-25 Location # 383295 in Garfield County Colorado. Location is within High Priority/Black Bear Habitat areas/Greater Sage Grouse General Habitat Management Area & in close proximity to Density/NSO habitat areas. While there, I observed normal production operations.</p> <p>During this inspection/audit the following compliance issues were observed:</p> <ol style="list-style-type: none"> 1. Fencing - Fencing needs maintenance/wildlife hazard & loose barbed wire in the interim area/wildlife & personnel hazard - Comply with rule 602 with a CA date of 09/07/2025 2. Equipment - Meter calibration info not conspicuously posted - Comply with rule 430 with a CA date of 09/10/2025 3. Equipment - Open ended piping near wellhead/wildlife hazard - Comply with rule 602 with a CA date of 09/07/2025 4. Inspected Facilities - Well lacks wellbore diagram - Comply with rule 420 with a CA date of 09/30/2025 5. Stormwater - Failure to minimize erosion & transport of sediment/insufficient BMP's - Comply with rule 1002 with a CA date of 09/15/2025 <p>A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules. This is a summary of inspection/audit report.</p>	smelserw	08/31/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708907343	Inspection/Audit 708907342 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7213460
708907344	Inspection/Audit 708907342 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7213461