

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/06/2025

Submitted Date:

08/25/2025

Document Number:

701104239

**FIELD INSPECTION FORM**

Loc ID 316408 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

2 Number of Comments  
1 Number of Corrective Actions

Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	ECMCInspectionReports@flywheelenergy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272887	WELL	PR	08/01/2024	GW	103-10454	FEDERAL RGU 23-7-297	EG
478941	WELL	PR	01/09/2025	OW	103-12476	FEDERAL RG 412-7-297	EG
478942	WELL	PR	01/28/2025	OW	103-12477	FEDERAL RG 12-18-297	EG
478943	WELL	PR	01/14/2024	OW	103-12478	FEDERAL RG 411-18-297	EG
478944	WELL	PR	10/01/2024	OW	103-12479	FEDERAL RG 313-7-297	EG
478945	WELL	PR	06/01/2024	OW	103-12480	FEDERAL RG 12-7-297	EG
478946	WELL	PR	10/01/2024	OW	103-12481	FEDERAL RG 13-7-297	EG
478947	WELL	PR	01/28/2025	OW	103-12482	FEDERAL RG 511-18-297	EG
478948	WELL	PR	12/10/2024	OW	103-12483	FEDERAL RG 514-7-297	EG
478949	WELL	PR	05/01/2024	OW	103-12484	FEDERAL RG 512-7-297	EG
478950	WELL	PR	10/01/2024	OW	103-12485	FEDERAL RG 314-7-297	EG
478951	WELL	PR	11/01/2024	OW	103-12486	FEDERAL RG 11-18-297	EG
478952	WELL	PR	06/01/2024	OW	103-12487	FEDERAL RG 312-7-297	EG
478953	WELL	PR	12/10/2024	OW	103-12488	FEDERAL RG 414-7-297	EG
478954	WELL	PR	01/28/2025	OW	103-12489	FEDERAL RG 311-18-297	EG

**General Comment:**

Flowline Integrity Inspection  
Frac water supply poly pipe runs across north edge of location.  
Unused poly lines laying near vault. Some unused pipes on south edge of location.

**Location**

<b>Lease Road:</b>			
Type			
comment:			
Corrective ActionL		Date:	

Overall Good:

<b>Emergency Contact Number:</b>	
Comment:	<input style="width: 80%;" type="text"/>
Corrective Action:	<input style="width: 80%;" type="text"/>
	Date: _____

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Unused poly lines laying near vault. Some unused pipes on south edge of location.		
Corrective Action:	Comply with Rule 606	Date:	09/06/2025

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: <u>272887</u>	Type: <u>WELL</u>	API Number: <u>103-10454</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: <u>478941</u>	Type: <u>WELL</u>	API Number: <u>103-12476</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: <u>478942</u>	Type: <u>WELL</u>	API Number: <u>103-12477</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: <u>478943</u>	Type: <u>WELL</u>	API Number: <u>103-12478</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: <u>478944</u>	Type: <u>WELL</u>	API Number: <u>103-12479</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: <u>478945</u>	Type: <u>WELL</u>	API Number: <u>103-12480</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: <u>478946</u>	Type: <u>WELL</u>	API Number: <u>103-12481</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: <u>478947</u>	Type: <u>WELL</u>	API Number: <u>103-12482</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: <u>478948</u>	Type: <u>WELL</u>	API Number: <u>103-12483</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: <u>478949</u>	Type: <u>WELL</u>	API Number: <u>103-12484</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: <u>478950</u>	Type: <u>WELL</u>	API Number: <u>103-12485</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: <u>478951</u>	Type: <u>WELL</u>	API Number: <u>103-12486</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: <u>478952</u>	Type: <u>WELL</u>	API Number: <u>103-12487</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: <u>478953</u>	Type: <u>WELL</u>	API Number: <u>103-12488</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: <u>478954</u>	Type: <u>WELL</u>	API Number: <u>103-12489</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404328951	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7203454">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7203454</a>
701104240	Flowline integrity inspection 701104239 photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7203453">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7203453</a>