

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/15/2025

Submitted Date:

08/25/2025

Document Number:

718100734

**FIELD INSPECTION FORM**

Loc ID: 485981      Inspector Name: Trujillo, Aaron      On-Site Inspection:       2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

13 Number of Comments

2 Number of Corrective Actions

Corrective Action Response Requested

**Operator Information:**

ECMC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER      State: CO      Zip: 80203

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Gaasche, Emily		emily.gaasche@state.co.us	
, Laramie		cogccnotifications@laramie-energy.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
485981	LOCATION	AC			-	Currier BCU 0993-16-07	RI

**General Comment:**

On 8/15/2025, Western Reclamation Work Lead Trujillo and NW Reclamation Specialist Gaasche conducted a pre-drill construction and stormwater inspection at Laramie Energy LLC's Currier BCU/0993-16-07 location in Mesa County, Colorado.

The following compliance issues were observed during this inspection:  
-Stormwater

Refer to the Location Construction and Reclamation sections of this inspection report for additional details.

Refer to the photo-documentation attached to this report.

Any corrective action(s) from previous inspection that have not been addressed are still applicable.

**Location Construction**

Location ID: 485981      CDP: \_\_\_\_\_

Comment:

Corrective Action:       Date: \_\_\_\_\_

**Form 2A COAs:**

Comment:

Corrective Action:       Date: \_\_\_\_\_

**Wildlife BMPs:**

Comment:

"Avian Survey Report" included with permit information on site. ECMC is requesting a copy of the pre-construction nesting migratory bird survey, as well as all nesting migratory bird survey documentation (data sheets, points, photographs, etc...), and details regarding the survey/transect methods used.

Please select the "Route to the Area Reclamation Specialist" checkbox within the "Reclamation" section of the Form 4.

Corrective Action: **Submit, attached to a Form 4, a copy of the pre-construction nesting migratory bird survey, as well as all nesting migratory bird survey documentation (data sheets, points, photographs, etc...), and details regarding the survey/transect methods used.**

Date: 09/12/2025

**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present
WADDLES	Yes		

Comments: Erosion BMPs: **Erosion logs implemented along the majority of the disturbance area. There are sections however where the BMP has not been installed per good engineering practices.**

**Additionally, there are areas along the access road where BMPs are missing or insufficient.**

Other BMPs:

Corrective Action: **Comply with rule 1002.f.** Date: 08/29/2025

	No		
--	----	--	--

Comments: Erosion BMPs: **BMPs along slopes the access road have not been installed; construction activities "in process" at time of inspection. Control measures to stabilize the slopes, as well as to minimize erosion and degradation will be required upon completion of construction activities.**

Other BMPs:

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

--	--	--	--

Comments: Erosion BMPs: **Fugitive dust concerns apparent along the access road. Water truck observed within the nearby areas of the Location, though not in use.**

**Maintenance advised.**

Other BMPs:

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Comment:** Initial construction activities in-process at time of inspection. A follow-up inspection will be conducted to determine compliance with Rule 1002.f and Operators Form 2A SWMP.

**Corrective Action:**  **Date:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Inspected Facilities**

Facility ID: 485981 Type: LOCATION API Number: - Status: AC Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND \_\_\_\_\_ In \_\_\_\_\_

Comment Initial grubbing and soil salvage activities "in process" at time of inspection. Pursuant to Operators Topsoil Protection Plan, topsoil depth was determined to be up to 24 inches within areas of the Location. Pursuant to Rule 1002.b, Operators shall salvage all of the topsoil horizon or the top six (6) inches, whichever is deeper. A follow-up inspection will be conducted to determine compliance with 1002.b requirements.

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_ In Process \_\_\_\_\_

Comment Pursuant to Form 2A COAs: topsoil stockpiles will be separated by compacted earthen berms, sediment control logs, straw bale barriers, etc. Stockpiles will be stabilized via surface roughening, applying hydro-seed/mulch, using soil tackifier, covering stockpiles with rolled erosion control products or other similar measures; topsoil stockpiles will be indicated on site with signage. A follow-up inspection will be conducted to determine compliance with Rule 1002.c requirements.

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RANGELAND \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action:

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID:	Lat:	Long:
Reference Point: _____	Other: _____	Length: _____	Width: _____	

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment: [Form 15 #404313085 submitted to permit the cuttings trench; form in process at time of inspection.](#)

Corrective Action

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: \_\_\_\_\_ Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: \_\_\_\_\_ 2+ feet Freeboard: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**ECMC Comments**

Comment	User	Date
<a href="#">Location signage (per Rule 605.a) and access road signage (per Rule 406.d) posted, though it is noted that the "date of commencement of construction" has not been posted.</a>	trujilloam	08/25/2025
<a href="#">The permitted size of disturbance area during construction, per Form 2A #403339067 is 9 acres.</a>	trujilloam	08/25/2025
<a href="#">Operator has delineated the perimeter of the Location; with use of a sUAS, the disturbance area at time of inspection was measured to be 9 acres.</a>		

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404329569	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7204027">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7204027</a>
718100735	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7204014">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7204014</a>