

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 262-25 Pad

Location ID: 335086




Photo # 3374 From entrance to location

Photo # 3375 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 262-25 Pad

Location ID: 335086



Photo # 3376 Location



Photo # 3377 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 262-25 Pad

Location ID: 335086



Aug 24, 2025 at 2:55:56 PM
+39.499850,-108.164053



Aug 24, 2025 at 3:11:26 PM
+39.499823,-108.164508

Photo # 3378 Location

Photo # 3379 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 262-25 Pad

Location ID: 335086



Photo # 3380 Methanol tank lacks required labeling



Photo # 3381 Methanol tank lacks required labeling

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 262-25 Pad

Location ID: 335086



**Photo # 3382 Flowline heating insulation open ended/
wildlife hazard – additionally there appears to be a possible
nest inside**



**Photo # 3383 Flowline heating insulation open ended/
wildlife hazard – additionally there appears to be a possible
nest inside**

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 262-25 Pad

Location ID: 335086



Photo # 3384 Hole in secondary containment liner/liner needs maintenance



Photo # 3385 Hole in secondary containment liner/liner needs maintenance

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 262-25 Pad

Location ID: 335086



Photo # 3386 Hole in secondary containment liner/liner needs maintenance



Photo # 3387 Hole in secondary containment liner/liner needs maintenance

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 262-25 Pad

Location ID: 335086



Photo # 3388 Hole in secondary containment liner/liner needs maintenance



Photo # 3389 Hole in secondary containment liner/liner needs maintenance

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 262-25 Pad

Location ID: 335086



**Photo # 3390 Secondary containment inadequately sized
/not in compliance with CECMC rules**