

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON/TEXACO 24C-12D Pad

Location #: 335774



Photo # 4466 From entrance to location



Photo # 4467 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON/TEXACO 24C-12D Pad

Location #: 335774




Photo # 4468 Location



Photo # 4469 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON/TEXACO 24C-12D Pad

Location #: 335774



Photo # 4470 Location



Photo # 4471 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON/TEXACO 24C-12D Pad

Location #: 335774



Photo # 4472 Location



Photo # 4473 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON/TEXACO 24C-12D Pad

Location #: 335774



Photo # 4474 Unmarked deadman



Photo # 4475 Same unmarked deadman

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON/TEXACO 24C-12D Pad

Location #: 335774



Photo # 4476 PRV vent line on fluid knockout for thermogen does not comply with CECMC pressure safety device rules



Photo # 4477 PRV vent line on fluid knockout for thermogen does not comply with CECMC pressure safety device rules