

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/03/2025

Submitted Date:

08/26/2025

Document Number:

694500800

FIELD INSPECTION FORM

Loc ID 312753 Inspector Name: NEIDEL, KRIS On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10386
Name of Operator: POC-I LLC
Address: P.O. BOX 51208
City: CASPER State: WY Zip: 82605

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Chamard, Megan		megan.chamard@state.co.us	
Podio, Rebecca	307-746-6468	rpodio@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222175	WELL	SI	02/01/2023	OW	081-05106	ILES DOME UNIT 26	EI

General Comment:

On 8/15/2025, ECMC staff; Kris Neidel inspected Iles #26.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

The following was observed: oily stained soil at wellhead, well SI.

Corrective Actions: The Iles field has been shut in since January 2023. It is suggested that the operator install mechanical intervention to prevent any valves from being opened or valve creep from occurring.

See Attached Photos.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:				
Type	Area	Volume		
PW/CO	WELLHEAD			
Comment: Oily soil at wellhead				
Corrective Action: Remove oily soil and delineate soil at wellhead to Table 915-1.			Date:	<u>10/07/2025</u>

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:	<input type="text"/>		
Corrective Action:		Date:	

Flaring:

Type		
Comment:	<input type="text"/>	
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 222175 Type: WELL API Number: 081-05106 Status: SI Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404331708	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7206152
694500801	photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7206145