

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/15/2025

Submitted Date:

08/26/2025

Document Number:

694500803

**FIELD INSPECTION FORM**

Loc ID 312751 Inspector Name: NEIDEL, KRIS On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10386  
 Name of Operator: POC-I LLC  
 Address: P.O. BOX 51208  
 City: CASPER State: WY Zip: 82605

**Findings:**

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Chamard, Megan		megan.chamard@state.co.us	
Podio, Rebecca	307-746-6468	rpodio@gmail.com	
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222170	WELL	SI	02/01/2023	OW	081-05093	ILES DOME UNIT 22	EI

**General Comment:**

On 8/15/2025, ECMC staff; Kris Neidel inspected Iles #22.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

The following was observed: oily stained soil inside wellhead enclosure, well SI.

Corrective Actions: The Iles field has been shut in since January 2023. It is suggested that the operator install mechanical intervention to prevent any valves from being opened or valve creep from occurring.

See Attached Photos.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		
PW/CO	WELLHEAD			
Comment: <span style="color: blue;">Oily soil at wellhead.</span>				
Corrective Action: <span style="color: red;">Remove and delineate oily soil at wellhead for TAbLe 915-1.</span>			Date:	<u>10/07/2025</u>

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:	<input type="text"/>		
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:	<input type="text"/>	
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 222170 Type: WELL API Number: 081-05093 Status: SI Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404331710	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7206153">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7206153</a>
694500804	photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7206146">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7206146</a>