

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/28/2025

Submitted Date:

09/02/2025

Document Number:

719000542

FIELD INSPECTION FORM

Loc ID: 325253 Inspector Name: GARCIA, CHARLES On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 96735
Name of Operator: WILLIFORD RESOURCES LLC
Address: 6506 S LEWIS AVE STE 102
City: TULSA State: OK Zip: 74136

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, GENERAL		hwilli@swbell.net	
,		glennstevens95@gmail.com	
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214405	WELL	SI	01/01/2023	OW	067-06005	WHEELER 1	SI

General Comment:

Inspection Report Summary
On 9/2/25 I Inspector Charles Garcia conducted an on-site inspection.
Location: WHEELER 1
Operator: WILLIFORD RESOURCES
API#: 067-06005
County: LaPlata

Location					
Overall Good: <input checked="" type="checkbox"/>					
Signs/Marker:					
Type		WELLHEAD			
Comment:		LOCATION SIGN			
Corrective Action:				Date:	
Emergency Contact Number:					
Comment:		918-712-8828 911 EMERGENCY			
Corrective Action:				Date:	
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment: <input style="width: 100%;" type="text"/>					
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type		PUMP JACK			
Comment:		CATTLE PANELS			
Corrective Action:				Date:	
Equipment:					
					corrective date
Type: Pump Jack		# 1			
Comment:					
Corrective Action:				Date:	
Type: Prime Mover		# 1			
Comment:		GAS			
Corrective Action:				Date:	
Type: Other		# 1			
Comment:		WELLHEAD			
Corrective Action:				Date:	
Type: Bradenhead		# 1			
Comment:					
Corrective Action:				Date:	
Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLs	PBV STEEL		37.128100,-108.077000
Comment:		TANK HAS NO PAINT AND RUSTING			
Corrective Action:		600.b MAINTAIN TANK PAINT			Date: 11/02/2025
Paint					
Condition	Inadequate				

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 214405 Type: WELL API Number: 067-06005 Status: SI Insp. Status: SI

BradenHead

Date of Last Brhd Test: 07/23/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 45 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000554	LOCATION PICTURES	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7215759