

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/02/2025

Submitted Date:

09/02/2025

Document Number:

719000559

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: GARCIA, CHARLES On-Site Inspection
 325251 _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96735
 Name of Operator: WILLIFORD RESOURCES LLC
 Address: 6506 S LEWIS AVE STE 102
 City: TULSA State: OK Zip: 74136

Findings:

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, GENERAL		hwilli@swbell.net	
Labowskie, Steve		steve.labowskie@state.co.us	
,		glennstevens95@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214401	WELL	SI	02/01/2025	OW	067-06001	LONG & SCHLUTER 2	SI

General Comment:

Inspection Report Summary
 On 9/2/25 I Inspector Charles Garcia
 conducted an on-site inspection.
 Location: LONG & SCHLUTER 2
 Operator: WILLIFORD RESOURCES
 API#: 067-06001
 County: LaPlata

Location					
Overall Good: <input checked="" type="checkbox"/>					
Signs/Marker:					
Type		WELLHEAD			
Comment:		LOCATION SIGN			
Corrective Action:				Date:	
Emergency Contact Number:					
Comment:		918-712-8828 911 EMERGENCY			
Corrective Action:				Date:	
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment: <input style="width: 100%;" type="text"/>					
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type		PUMP JACK			
Comment:		CATTLEPANELS			
Corrective Action:				Date:	
Equipment:					
					corrective date
Type: Pump Jack		# 1			
Comment:					
Corrective Action:				Date:	
Type: Bradenhead		# 1			
Comment:					
Corrective Action:				Date:	
Type: Other		# 1			
Comment:		WELLHEAD			
Corrective Action:				Date:	
Type: Prime Mover		# 1			
Comment:		GAS			
Corrective Action:				Date:	
Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	PBV STEEL		37.121000,-108.087100
Comment:		NO PAINT IN SPOTS STARTING TO RUST			
Corrective Action:		600.b MAINTAIN TANK PAINT			Date:
					12/02/2025
Paint					
Condition	Inadequate				

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 214401 Type: WELL API Number: 067-06001 Status: SI Insp. Status: SI

Producing Well

Comment: WELL SHOWING SHUT IN STATUS HOW EVER WELL WAS RUNNING WHEN I ARRIVED TO LOCATION

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/28/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000560	LOCATION PICTURES	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7215765