

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/02/2025

Submitted Date:

09/02/2025

Document Number:

719000552

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
325405 _____ GARCIA, CHARLES _____ 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 96735
Name of Operator: WILLIFORD RESOURCES LLC
Address: 6506 S LEWIS AVE STE 102
City: TULSA State: OK Zip: 74136

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		glennstevens95@gmail.com	
, GENERAL		hwilli@swbell.net	
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214720	WELL	SI	02/01/2025	OW	067-06324	HAZEL 2	SI

General Comment:

Inspection Report Summary
On 9/2/25 I Inspector Charles Garcia conducted an on-site inspection.
Location: HAZEL 2
Operator: WILLIFORD RESOURCES
API#: 067-06324
County: LaPlata

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	LOCATION SIGN		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	918-712-8828 911 EMERGENCY		Date:
Corrective Action:			
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	CATTLE PANELS		
Corrective Action:			Date:
Equipment:			
			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	WELLHEAD		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	GAS		
Corrective Action:			Date:
Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			

Corrective Action:

Date:

Inspected Facilities

Facility ID: 214720 Type: WELL API Number: 067-06324 Status: SI Insp. Status: SI

Producing Well

Comment: WELL SHOWING SHUT IN STATUS HOW EVER WELL WAS RUNNING WHEN I ARRIVED TO LOCATION

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/24/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 23 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000553	LOCATION PICTURES	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7215762