

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC UNION PACIFIC #126 X 32 PAD

Location ID: 311821

Date: 08/26/2025



Photo # 2596 Entrance to location



Photo # 2597 Location

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC UNION PACIFIC #126 X 32 PAD

Location ID: 311821

Date: 08/26/2025




Photo # 2598 Location



Photo # 2621 SE corner of location

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC UNION PACIFIC #126 X 32 PAD

Location ID: 311821

Date: 08/26/2025



Photo # 2622 SW corner of location

Photo # 2623 NE corner of location

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC UNION PACIFIC #126 X 32 PAD

Location ID: 311821

Date: 08/26/2025



Photo # 2624 NW corner of location



Photo # 2603 Unused flowline lacks lockout tagout (OOSLAT)

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC UNION PACIFIC #126 X 32 PAD

Location ID: 311821

Date: 08/26/2025



Photo # 2605 Berm needs maintenance



Photo # 2608 Berm needs maintenance

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC UNION PACIFIC #126 X 32 PAD

Location ID: 311821

Date: 08/26/2025



Photo # 2612 Wattles need maintenance



Photo # 2613 Wattles need maintenance

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC UNION PACIFIC #126 X 32 PAD

Location ID: 311821

Date: 08/26/2025



Photo # 2614 Debris



Photo # 2615 Debris

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC UNION PACIFIC #126 X 32 PAD

Location ID: 311821

Date: 08/26/2025



Photo # 2617 Debris



Photo # 2618 Debris

## Inspection/Audit Photos

Location: SCOUT ENERGY MANAGEMENT LLC UNION PACIFIC #126 X 32 PAD

Location ID: 311821

Date: 08/26/2025



Photo # 2620 Debris