

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/22/2025

Submitted Date:

08/27/2025

Document Number:

701104244

**FIELD INSPECTION FORM**

Loc ID: 421340 Inspector Name: LONGWORTH, MIKE On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10433  
Name of Operator: LARAMIE ENERGY LLC  
Address: 1700 LINCOLN ST STE 3950  
City: DENVER State: CO Zip: 80203

**Findings:**

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
COGCC, Laramie	970-248-0497	cogccnotifications@laramie-energy.com	All inspections
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
421341	WELL	PR	04/30/2012	GW	045-20360	Cascade Creek 697-05-28B	EG

**General Comment:**

Flowline Integrity Inspection  
A 3" buried poly line has been cut off and left running under surface down to CC 0605-02 Pad ID# 323998. Line is open ended with no OOSLAT in place.  
Register flowline and out of service flowline must be abandoned per COGCC rule 1105 by 9/15/25  
OOSLAT out of service flowline by no later than end of the day 8/28/25  
2 Frac lines were removed from east side location running down to the CC 0605-02 Pad ID# 323998. Top segments of frac lines were left.  
Comply with 606 by 9/15/25

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good:

Emergency Contact Number:	
Comment:	<input style="width: 50%;" type="text"/>
Corrective Action:	<input style="width: 50%;" type="text"/> Date: _____

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	2 Frac lines were removed from east side location running down to the CC 0605-02 Pad ID# 323998. Top segments of frac lines were left.		
Corrective Action:	Comply with 606	Date:	09/15/2025

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 421341 Type: WELL API Number: 045-20360 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404333695	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7207946">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7207946</a>
701104245	Flowline integrity inspection 701104244 photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7207939">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7207939</a>