

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/13/2025

Submitted Date:

08/27/2025

Document Number:

709100548

FIELD INSPECTION FORM

Loc ID 313811 Inspector Name: Heibel, Krystal On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 31257
Name of Operator: FRITZLER RESOURCES INC
Address: P O BOX 114
City: FORT MORGAN State: CO Zip: 80701

Findings:

- 11 Number of Comments
- 7 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Anthony Dunnam		anthony.dunnam@state.co.us	
Kyle Waggoner		kyle.waggoner@state.co.us	
Krystal Heibel		krystal.heibel@state.co.us	
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
102692	PIT	AC			-	MENKE	EI
102693	PIT	AC			-	MENKE	EI
102694	PIT	AC			-	MENKE	EI
225296	WELL	PR	02/01/2025	OW	087-05698	MENKE 4	EI
313811	LOCATION	AC			-	MENKE-62N55W 22NENW	EI

General Comment:

On August 13, 2025, ECMC Environmental Unit Staff Krystal Heibel inspected the Menke-62N55W/22NENW location (Facility ID: 313811) and the Menke #4 wellhead (API 05-087-05698).

Location			
Lease Road:			
Type			
comment:	Lease road maintained.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	No signage present on partially buried vessels next to pit.		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 11/13/2025
Type	TANK LABELS/PLACARDS		
Comment:	NFPA placard signage not visible and fading among tanks / Install new placards that are visible from a distance		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Good Housekeeping:			
Type	TRASH		
Comment:	Trash and unused debris located at the facility.		
Corrective Action:	Comply with Rule 606		Date: 08/27/2025
Type			
Comment:	Weeds present among pit berms		
Corrective Action:	Comply with Rule 606		Date: 08/27/2025
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
Comment:	Hydrocarbon stained soil observed throughout the tank battery facility, surrounding the pit berms, and within and around the pump jack's metal shed. It appears fresh soil has been placed on top of the hydrocarbon stained soil located within the metal shed.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. Report spill or release of E&P waste or produced fluids Remove free fluids and contact ECMC EPS staff per Rule 912.b.		Date: 08/18/2025
In Containment: No _____			
Comment: <input style="width: 100%;" type="text"/>			
<input checked="" type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type:	#		corrective date
Comment:	Less than 2-feet of freeboard observed within the pit.		
Corrective Action:	Lower fluid level so at least two feet of freeboard exists per Rule 909.c.		Date: 08/09/2025
Venting:			

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 102692 Type: PIT API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 102693 Type: PIT API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 102694 Type: PIT API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 225296 Type: WELL API Number: 087-05698 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 313811 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)	
Comment	No BMPs in place to control stormwater runoff. (See photos 8 and 18 in Menke 4 Photo log)				
Corrective Action	Install BMPs in accordance with 1002.f.(2) to prevent runoff and completely contain impacts.				Date: 09/13/2025

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID:	Lat:	Long:
-------	--------	---------	------	-------

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: The earthen pit on location is unregistered with the current operator.

Corrective Action No pit permit on file under current Operator for Production Pit observed on location. Submit an eForm 15 Pit Permit Report to update ECMC records with current information and demonstrate compliance with Rules 908, 909, and 910, specifically Rule 909.b. Include Produced Water Quality Analyses data required by Rule 909.j. as an attachment to the Form 15.

Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action

Date: _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404331946	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7206604
709100549	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7206601
709100550	Wellhead photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7206602