

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/02/2025

Submitted Date:

09/02/2025

Document Number:

708907373

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

18 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Contact Information:**

Contact Name	Phone	Email	Comment
TEP		ECMCInspectionReports@flywheelenergy.com	
Heil, John		john.heil@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
467146	GAS COMPRESSOR STATION	AC			-	CS_Wasatch	AC

**General Comment:**

[This is a Field Inspection/Audit of the scout card, related documents and the location.](#)

**Location**

<b>Lease Road:</b>			
	Type Access		
comment:			
Corrective ActionL			Date:

Overall Good:

<b>Signs/Marker:</b>			
	Type CONTAINERS		
Comment:	Chemical tank		
Corrective Action:			Date:
	Type TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
	Type OTHER		
Comment:	Sign at entrance to location		
Corrective Action:			Date:
	Type BATTERY		
Comment:	No tank battery on location		
Corrective Action:			Date:

Emergency Contact Number:			
	Comment: 911/970-285-9377		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Cataflow		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		

Comment:	Chemical tank	Date:	
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Fire extinguisher	Date:	
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	<50 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	Antifreeze
Other (Capacity)	500 gal
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			
Comment:	Separate containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	<50 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	Engine oil
Other (Capacity)	500 gal
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			
Comment:	Separate containment			
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

**Flaring:**

Type	
------	--

Comment:		
Corrective Action:	Date:	

**Inspected Facilities**

Facility ID: 467146 Type: GAS API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				Light compaction in some sections
		Ditches				
		Gravel				Sparse to none in most sections
		Culverts				
Berms						
		Tracking Pad				Aggregate/gravel based VTC
Gravel						Sparse to none in most areas
Compaction						Light compaction
				Material Handling And Spill Prevention		Chemical tank containment

Comment: Aggregate/gravel based VTC at intersection of public road & start of lease road. Dimensions & details are as follows approximately 75 ft long, 27 ft wide & varying depths from 1-3 inches, depth insufficient, area does not appear to have been excavated & no class 2 geotextile fabric observed.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p><span style="color: blue;">CECMC Inspection/Audit Report Summary On 09/02/2025 at approximately 12:08 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection/audit at TEP ROCKY MOUNTAIN LLC CS_Wasatch Compressor Station. Facility # 467146 in Garfield County Colorado. Location is within High Priority/Density/Black Bear Habitat areas/Bald Eagle Roost Site &amp; in close proximity to NSO Habitat area. Location is within Rule 411a Surface Water Intermediate Buffer. Location is approximately 418 yards from Rule 411b Generalized External Buffer. Location is approximately 424 yards from the Colorado River. While there, I observed normal production operations.</span></p> <p><span style="color: blue;">This is a summary of inspection/audit report.</span></p>	smelserw	09/02/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708907374	Inspection/Audit 708907373 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7215956">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7215956</a>
708907375	Inspection/Audit 708907373 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7215957">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7215957</a>