

# Inspection Photos

08/22/2025

**Operator:** QB Energy Operating LLC #10844

**Location ID:** 421020

**Inspection Doc:** 719200139

Garfield County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 421020



**Photo 1:** Photos show an overview of the location looking north and east, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 421020



**Photo 2:** Photos show an overview of the location looking southeast and southwest, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 421020



**Photo 3:** Photo showing bindweed is present on the southeastern edge of the upper working pad surface. Comply with Rules 1003.f. and 606.c.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 421020



**Photo 4:** Photos show an overview of the lower working pad surface of the location looking northwest and northeast, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 421020



**Photo 5:** Photos show an overview of the lower working pad surface of the location looking southeast and southwest, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 421020



**Photo 6:** Photo showing kochia is present on the northeastern edge of the lower working pad surface. Comply with Rule 606.c.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 421020



**Photo 7:** Photos showing that some patches on the secondary containment liner are in disrepair and are not sufficiently impervious to contain a spill or release. Refer to previous inspections for Corrective Action.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 421020



**Photo 8:** Photos showing a cut slope in between the upper and lower working pad surface that appears to have been hydromulched recently.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 421020



**Photo 9:** Photo showing an overview of the western interim area. Interim areas appear to be progressing towards 1003 reclamation standards.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources