

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/26/2025

Submitted Date:

08/29/2025

Document Number:

715202831

**FIELD INSPECTION FORM**

Loc ID 380893 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10791  
Name of Operator: WAVETECH HELIUM INC  
Address: 1801 BROADWAY SUITE 600  
City: DENVER State: CO Zip: 80202

**Findings:**

15 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Jobe, Patrick	(303) 534-3383	pjobe@wavetechenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208175	WELL	PR	05/01/2025	DA	017-07110	UPRC 1 Rosa 31-10	PR

**General Comment:**

[This is a field audit of the scout card, related documents and the location by SE Compliance Specialist Brian Welsh](#)

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Dirt road through farm ground		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by road at location entrance		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on tanks		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Prime mover on east side of tanks needs removed from location		
Corrective Action:			Date:
Type	WEEDS		
Comment:	Weeds across location need maintenance		
Corrective Action:	Comply with rule 606		Date: 09/26/2025
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Vertical Separator	# 1		corrective date
Comment:	Vertical gas separator on west side of tanks inside berms		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Meter run on east side of wellhead		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Weatherford 640		
Corrective Action:			Date:

Type: Prime Mover	# 1	
Comment:	6 cyl Arrow motor	
Corrective Action:		Date:
Type: Ancillary equipment	# 3	
Comment:	Telemetry equipment, gas scrubber and propane tank	
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment:	48" ECD on north side of meter shed	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLs	FIBERGLASS AST		39.029850,-102.211810
Comment:	2-Production water tanks on the south side of the pumping unit				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Plastic lined berms			
Corrective Action:				Date:

**Venting:**

Yes/No	
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 208175 Type: WELL API Number: 017-07110 Status: PR Insp. Status: PR

**Producing Well**

Comment: Well is PR at time of inspection. Production reports are up to date at time of inspection

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404336529	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7211788">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7211788</a>
715202871	location photo	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7211772">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7211772</a>