

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/26/2025

Submitted Date:

08/29/2025

Document Number:

715202832

**FIELD INSPECTION FORM**

Loc ID 485672 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10791  
Name of Operator: WAVETECH HELIUM INC  
Address: 1801 BROADWAY SUITE 600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 14 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name  | Phone          | Email                    | Comment |
|---------------|----------------|--------------------------|---------|
| Jobe, Patrick | (303) 534-3383 | pjobe@wavetechenergy.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name                         | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------------------------|-------------|
| 486311      | WELL | PR     | 06/01/2025  | LO         | 017-07820 | 1 Wavetech FPI Burlington Farms 32-11 | PR          |

**General Comment:**

[This is a field audit of the scout card, related documents and the location by SE Compliance Specialist Brian Welsh](#)

**Location**

|                    |                               |  |       |
|--------------------|-------------------------------|--|-------|
| <b>Lease Road:</b> |                               |  |       |
| Type               | Access                        |  |       |
| comment:           | Dirt road through farm ground |  |       |
| Corrective Action  |                               |  | Date: |

Overall Good:

|                      |   |  |                  |
|----------------------|---|--|------------------|
| <b>Signs/Marker:</b> |   |  |                  |
| Type                 | WELLHEAD                                  |  |                  |
| Comment:             | Lease sign by access at location entrance |  |                  |
| Corrective Action:   |   |  | Date:            |
| Type                 | TANK LABELS/PLACARDS                      |  |                  |
| Comment:             | No labeling on production tank            |  |                  |
| Corrective Action:   | Install sign to comply with Rule 605.h.   |  | Date: 09/26/2025 |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

Multiple Spills and Releases?

|                           |   |  |                 |
|---------------------------|---|--|-----------------|
| <b>Equipment:</b>         |   |  | corrective date |
| Type: Compressor          | # 1   |  |                 |
| Comment:                  | Skid mounted V8 driven booster compressor on south side of tank |  |                 |
| Corrective Action:        |   |  | Date:           |
| Type: Flare               | # 0   |  |                 |
| Comment:                  | Flare has been removed from location                            |  |                 |
| Corrective Action:        |   |  | Date:           |
| Type: Vertical Separator  | # 1   |  |                 |
| Comment:                  | Vertical gas separator on east side of tank inside berms        |  |                 |
| Corrective Action:        |   |  | Date:           |
| Type: Gas Meter Run       | # 1   |  |                 |
| Comment:                  | Meter shed on west side of tank                                 |  |                 |
| Corrective Action:        |   |  | Date:           |
| Type: Other               | # 0   |  |                 |
| Comment:                  | Well testing equipment has been removed                         |  |                 |
| Corrective Action:        |   |  | Date:           |
| Type: Ancillary equipment | # 1   |  |                 |

|  |       |
|--|-------|
| Comment: <a href="#">Telemetry equipment at meter shed</a> |       |
| Corrective Action:   | Date: |

**Tanks and Berms:**

| Contents  | # | Capacity | Type | Tank ID | SE GPS                |
|---|---|----------|------|---------|-----------------------|
| OTHER   | 0 | 500 BBLs | LVST |         | 39.028000,-102.193020 |
| Comment: <a href="#">Frac tank has been removed from location</a> |   |          |      |         |                       |
| Corrective Action:  |   |          |      |         | Date:                 |

**Paint**

|                  |  |  |  |  |  |
|------------------|--|--|--|--|--|
| Condition        |  |  |  |  |  |
| Other (Content)  |  |  |  |  |  |
| Other (Capacity) |  |  |  |  |  |
| Other (Type)     |  |  |  |  |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents  | # | Capacity | Type           | Tank ID | SE GPS                |
|---|---|----------|----------------|---------|-----------------------|
| PRODUCED WATER  | 1 | 200 BBLs | FIBERGLASS AST |         | 39.028110,-102.192740 |
| Comment: <a href="#">Black produced water tank on east side of meter shed</a> |   |          |                |         |                       |
| Corrective Action:  |   |          |                |         | Date:                 |

**Paint**

|                  |  |  |  |  |  |
|------------------|--|--|--|--|--|
| Condition        |  |  |  |  |  |
| Other (Content)  |  |  |  |  |  |
| Other (Capacity) |  |  |  |  |  |
| Other (Type)     |  |  |  |  |  |

**Berms**

| Type                                   | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--|----------|---------------------|---------------------|-------------|
| Earth                                  | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment: <a href="#">Plastic liner</a> |          |                     |                     |             |
| Corrective Action:                     |          |                     |                     | Date:       |

**Venting:**

|                    |  |  |  |       |
|--------------------|--|--|--|-------|
| Yes/No             |  |  |  |       |
| Comment:           |  |  |  |       |
| Corrective Action: |  |  |  | Date: |

**Flaring:**

|                    |  |  |  |       |
|--------------------|--|--|--|-------|
| Type               |  |  |  |       |
| Comment:           |  |  |  |       |
| Corrective Action: |  |  |  | Date: |

**Inspected Facilities**

Facility ID: 486311 Type: WELL API Number: 017-07820 Status: PR Insp. Status: PR

**Producing Well**

Comment: Well is SI at time of inspection. Production reports are up to date at time of inspection

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 404336530    | INSPECTION SUBMITTED | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7211789">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7211789</a> |
| 715202869    | location photo       | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7211773">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7211773</a> |
| 715202870    | tank battery         | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7211774">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7211774</a> |