

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/05/2025

Submitted Date:

09/05/2025

Document Number:

717300458

FIELD INSPECTION FORM

Loc ID 331701 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		ECMCInspections@Oxy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
331701	LOCATION	AC			-	NIX P 28-69HN	EG
426353	WELL	PR	03/01/2023	OW	123-34658	NIX P 28-69HN	PA

General Comment:

ECMC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 331701 Type: LOCATION API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 426353 Type: WELL API Number: 123-34658 Status: PR Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
As outlined on ECMC form 19 spill report Doc #404313599 received on 08/13/2025: While conducting wellhead plugging and abandonment at the NIX P28-69HN wellhead, historically impacted soil was discovered at the wellhead. The volume of the release is unknown. The wellhead has been plugged and abandoned.	maclarej	09/05/2025
As outlined on ECMC form 19 spill report Doc #404309784 received on 08/08/2025: On August 7, 2025, a release was discovered at the NIX P28-69HN Facility outside of the secondary containment. The release was caused by separator flushing activities.	maclarej	09/05/2025
Well is PA (Nix 28-69HN); ECMC form 42 notice of start of plugging operations doc #404173982 received on 04/22/2025. The off location flowline AIP is in progress; flowline riser at PA well is blind flanged. Facility/ battery serviced additional wells (PA); flowline risers at HHS are disconnected/ bull plugged. Battery decommissioning has not been started. Remediation work is in progress.	maclarej	09/05/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300459	Signage at PA well; FL riser (blind flanged)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7220393
717300460	FL risers at HHS; Isolated bullplugged	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7220394
717300461	Facility/ battery; Excavation at HHS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7220395