

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/04/2025

Submitted Date:

09/05/2025

Document Number:

717300457

FIELD INSPECTION FORM

Loc ID 327157 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		ECMCInspections@Oxy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246441	WELL	SI	05/01/2022	GW	123-14238	HSR-HERRICK 3-21	TA
484314	LOCATION	AC			-	Herrick 21-3N-66W NENW TB Location	EG

General Comment:

[ECMC Engineering Integrity Inspection; Flowline Inspection](#)
[Photos Uploaded](#)

Inspected Facilities

Facility ID: 246441 Type: WELL API Number: 123-14238 Status: SI Insp. Status: TA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 484314 Type: LOCATION API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Well (HSR Herrick 3-21) is Temporarily Abandoned; Off location flowline is disconnected/ isolated (air gap) at TA well and inlet to HHS. Equipment/ flowline valves are OOSLAT. No Oxy personnel on location at time of inspection.	maclarej	09/05/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300462	Tank battery and signage	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7221090
717300463	TA well and signage; OLF disconnected/ OOSLAT	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7221091
717300464	HHS; Flowline disconnected/ OOSLAT	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7221092