

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Logan Dehydration Facility

Facility #: 449282



Photo # 3828 Entrance to location



Photo # 3829 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Logan Dehydration Facility

Facility #: 449282



Photo # 3830 Location



Photo # 3831 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Logan Dehydration Facility

Facility #: 449282



Aug 25, 2025 at 1:05:38 PM  
+39.472147,-108.167710



Aug 25, 2025 at 1:04:24 PM  
+39.471919,-108.168131

Photo # 3832 Location

Photo # 3833 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Logan Dehydration Facility

Facility #: 449282



Photo # 3834 Location



Photo # 3835 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Logan Dehydration Facility

Facility #: 449282



Photo # 3836 Location



Photo # 3837 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Logan Dehydration Facility

Facility #: 449282



Aug 25, 2025 at 1:15:00 PM  
+39.472214,-108.168133



Aug 25, 2025 at 1:08:02 PM  
+39.472282,-108.167856

Photo # 3838 Location

Photo # 3839 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Logan Dehydration Facility

Facility #: 449282



Aug 25, 2025 at 1:15:08 PM  
+39.472214,-108.168133

Photo # 3840 Location



Aug 25, 2025 at 1:17:27 PM  
+39.472306,-108.168167

Photo # 3841 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Logan Dehydration Facility

Facility #: 449282



Photo # 3842 Location



Photo # 3843 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Logan Dehydration Facility

Facility #: 449282



Photo # 3844 Spill kit



Photo # 3845 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Logan Dehydration Facility

Facility #: 449282



Photo # 3846 Battery sign damaged & illegible



Photo # 3847 Secondary containment liner damaged/needs maintenance

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Logan Dehydration Facility

Facility #: 449282



**Photo # 3848 Secondary containment liner damaged/needs maintenance**



**Photo # 3849 Unused flowline lacks lockout tagout (OOSLAT)**

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Logan Dehydration Facility

Facility #: 449282



Photo # 3850 Unused flowline lacks lockout tagout (OOSLAT)



Photo # 3851 Unused flowlines lack lockout tagout (OOSLAT)

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Logan Dehydration Facility

Facility #: 449282



Photo # 3852 Unused flowlines lack lockout tagout (OOSLAT)



Photo # 3853 Unused flowlines lack lockout tagout (OOSLAT)

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Logan Dehydration Facility

Facility #: 449282



Photo # 3854 Chemical tank lacks required labeling



Photo # 3855 Chemical tank lacks required labeling

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Logan Dehydration Facility

Facility #: 449282



Photo # 3856 Chemical tank lacks required labeling



Photo # 3857 Chemical tank lacks required labeling

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Logan Dehydration Facility

Facility #: 449282



Photo # 3858 Chemical tank lacks required labeling



Photo # 3859 Chemical tank lacks required labeling

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Logan Dehydration Facility

Facility #: 449282



Aug 25, 2025 at 1:10:34 PM  
+39.472248,-108.167964



Aug 25, 2025 at 1:00:35 PM  
+39.471980,-108.168265

**Photo # 3860 Chemical tank lacks required labeling**

**Photo # 3861 Flowline heating insulation open ended  
/wildlife hazard/available for entry by wildlife**

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Logan Dehydration Facility

Facility #: 449282



Photo # 3862 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 3863 PRV vent line does not comply with CECMC pressure safety device rules

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Logan Dehydration Facility

Facility #: 449282



**Photo # 3864 PRV vent line does not comply with CECMC pressure safety device rules**



**Photo # 3865 PRV vent line does not comply with CECMC pressure safety device rules**

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Logan Dehydration Facility

Facility #: 449282



Photo # 3866 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 3867 PRV vent line does not comply with CECMC pressure safety device rules

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Logan Dehydration Facility

Facility #: 449282



**Photo # 3868 PRV vent line does not comply with CECMC pressure safety device rules**



**Photo # 3869 PRV vent line does not comply with CECMC pressure safety device rules**

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Logan Dehydration Facility

Facility #: 449282



Photo # 3870 Tank label has previous operators name



Photo # 3871 Tank label has previous operators name

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Logan Dehydration Facility

Facility #: 449282




Photo # 3872 Tank label has previous operators name

Photo # 3873 Tank label has previous operators name

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Logan Dehydration Facility

Facility #: 449282




Photo # 3874 Tank label has previous operators name

Photo # 3875 Staining in secondary containment



## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC Logan Dehydration Facility

Facility #: 449282



Facility overview