

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON E13 697

Location #: 311623



Photo # 6883 From entrance to location



Photo # 6884 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON E13 697

Location #: 311623



Photo # 6885 Location



Photo # 6886 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON E13 697

Location #: 311623



Photo # 6887 Location



Photo # 6888 Debris

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON E13 697

Location #: 311623



Sep 8, 2025 at 3:59:10 PM
+39.523606,-108.176313



Sep 8, 2025 at 3:59:13 PM
+39.523606,-108.176313

Photo # 6889 Open ended pipe on fire tube/wildlife hazard

Photo # 6890 Open ended pipe on fire tube/wildlife hazard

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON E13 697

Location #: 311623



Photo # 6891 Wellhead sign has previous operators name

Photo # 6892 Wellhead sign has previous operators name

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON E13 697

Location #: 311623



Photo # 6893 Battery sign has previous operators name



Photo # 6894 Sign at entrance to location has previous operators name

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON E13 697

Location #: 311623



Photo # 6895 Tank labels have previous operators name

Photo # 6896 Tank labels have previous operators name

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON E13 697

Location #: 311623



Photo # 6897 Tank label has previous operators name

Photo # 6898 Tank label has previous operators name

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON E13 697

Location #: 311623



Photo # 6899 Unused equipment



Photo # 6900 Unused equipment

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON E13 697

Location #: 311623



Photo # 6901 Secondary containment liner damaged/needs maintenance