

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/26/2025

Submitted Date:

09/02/2025

Document Number:

713401033

FIELD INSPECTION FORM

Loc ID 311821 Inspector Name: Popejoy, Dusty On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10779
Name of Operator: SCOUT ENERGY MANAGEMENT LLC
Address: 13800 MONTFORT DRIVE SUITE 100
City: DALLAS State: TX Zip: 75240

Findings:

- 14 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Rosado, Sydney		Sydney.Rosado@scoutep.com	
Saint, John		jsaint@scoutep.com	
Wiley, Mikel		Mikel.Wiley@scoutep.com	
Sanford, Anita		anita.sanford@scoutep.com	
Longworth, Mike		mike.longworth@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231182	WELL	PR	01/01/1999	OW	103-08851	UNION PACIFIC 126 X 32	PR

General Comment:

[This is a Field Inspection/audit of the scout card, related documents and the location.](#)

Location

Lease Road:			
	Type Access		
	comment: Access		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
	Type OTHER		
	Comment: Sign near entrance to location		
Corrective Action:			Date:
	Type WELLHEAD		
	Comment: Operator name is starting to peel. Sign also has some staining.		
Corrective Action:			Date:

Emergency Contact Number:			
	Comment: 970-675-3700/911		
Corrective Action:			Date: _____

Good Housekeeping:			
	Type DEBRIS		
	Comment: Debris on location, refer to photos		
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
	Comment: <input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			

Equipment:			corrective date
Type: Submersible Pump	# 1		
	Comment: ESP		
Corrective Action:			Date:
Type: Other	# 1		
	Comment: Unused flowline lacks lockout tagout (OOSLAT)		
Corrective Action:	Comply with CECMC 600 & 1100 series rules		Date: 09/09/2025
Type: Bradenhead	# 1		
	Comment: Bradenhead valve is accessible/equipped with gauge		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
	Comment:		
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 231182 Type: WELL API Number: 103-08851 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Fail					Wattles need maintenance
Berms	Fail					Berm needs maintenance

Comment: [1. Eroded berm on NW side of location/BMP's need maintenance](#)
[2. Stormwater undercutting wattles/BMP's need maintenance](#)

Corrective Action: [Comply with CECMC Stormwater rules](#)

Date: 09/17/2025

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary</p> <p>On 08/26/2025 at approximately 11:56 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at SCOUT ENERGY MANAGEMENT LLC UNION PACIFIC #126 X 32 PAD at Location ID #311821 in Rio Blanco County, Colorado.</p> <p>This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density Habitat regulations.</p> <p>While there, I observed normal production operations.</p> <p>During the inspection/audit, the following compliance issues were observed:</p> <ol style="list-style-type: none"> 1. Equipment - Unused flowline lacks lockout tagout (OOSLAT) with a CA date of 09/9/2025 2. Stormwater - Eroded berm & stormwater undercutting wattles/BMP's need maintenance with a CA date of 09/17/2025 <p>A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a summary of inspection/audit report.</p>	popejoyd	09/02/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404339286	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7215920
713401034	713401033 Inspection-Audit Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7215919