

Inspection Photos
Location Name: Hein 2
Location ID: 332959



Photo 1 Location has overgrown vegetation throughout.

Photo 2 ECD, Horizontal Heated Separator.

Inspection Photos
Location Name: Hein 2
Location ID: 332959




Photo 3 Tank Battery is overrun with vegetation .

Photo 4 Tank Battery sign.

Inspection Photos
Location Name: Hein 2
Location ID: 332959



Photo 5 Tank Battery is overrun with vegetation .



Photo 6 Tank Battery is overrun with vegetation ..

Inspection Photos
Location Name: Hein 2
Location ID: 332959



Photo 7 Wellsite is overrun with vegetation .

Photo 8 Wellsite sign.

Inspection Photos
Location Name: Hein 2
Location ID: 332959



Photo 9 Wellhead is overrun with vegetation .

Photo 10 Wellsite is overrun with vegetation.

Inspection Photos
Location Name: Hein 2
Location ID: 332959



Photo 11 Unmarked flow line is overrun with vegetation.

Photo 12 Horizontal separator is overrun with vegetation.

Inspection Photos
Location Name: Hein 2
Location ID: 332959



Photo 13 vertical separator is overrun with vegetation.

Photo 14 Gas Meter Run is overrun with vegetation.