

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/29/2025

Submitted Date:

09/03/2025

Document Number:

718100771

**FIELD INSPECTION FORM**

Loc ID: 490082 Inspector Name: Trujillo, Aaron On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10515  
Name of Operator: GUNNISON ENERGY LLC  
Address: 999 18TH STREET SUITE 1755N  
City: DENVER State: CO Zip: 80202

**Findings:**

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		geops@oxbow.com	<a href="#">Inspection mail box</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
490082	LOCATION	AC	05/07/2025		-	Gunnison Tank 11S90W	RI

**General Comment:**

On 8/29/2025, Western Reclamation Work Lead Trujillo conducted an inspection at Gunnison Energy LLC's Gunnison Tank 11S90W facility Location in Gunnison County, Colorado.

This inspection is a follow-up to #718100518 to document compliance with the following corrective actions:

- Good Housekeeping
- Weeds
- Signage requirements

It was observed in this inspection that the Location remains out of compliance with EMCM Rules and CA requirements.

Refer to the Location sections of this inspection report for additional details.

Refer to the photo-documentation attached to this report.

Any corrective action(s) from previous inspection that have not been addressed are still applicable.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	<p>Previous inspection observed that tank battery signage does not comport with Rule 605 requirements, and does not include information such as the well names and API number associated with the tank battery., and the legal location of the wells. Inspection required Operator to comply with Rule 605.e.</p> <p>It was observed in this inspection that signage remains out of compliance with Rule 605.e. This CA remains applicable.</p>		
Corrective Action:	Comply with Rule 605.e.		Date:
Type	TANK LABELS/PLACARDS		
Comment:	Signage/labeling at tank does not comport with 605 requirements.		
Corrective Action:			Date:

Emergency Contact Number:	
Comment:	<input type="text"/>
Corrective Action:	<input type="text"/>
	Date: _____

<b>Good Housekeeping:</b>			
Type			
Comment:	Various trash, debris and unused equipment documented within Inspection #718100518 appears to have been removed from the Location. This CA has been resolved.		
Corrective Action:			Date:
Type	WEEDS		
Comment:	<p>Previous inspection observed Undesirable and Noxious Plant Species (Common mullein and Musk thistle rosettes) observed established throughout the Location. Inspection required Operator to comply with Rule 606.c.</p> <p>Noxious weeds remain evident on the Location, however weed management efforts are apparent.</p> <p>Continue to monitor and manage weeds on the Location.</p>		
Corrective Action:			Date:

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type:	#		
Comment:	Open ended risers documented in Inspection #718100518 have been capped. This CA has been resolved.		
Corrective Action:			Date:

<b>Tanks and Berms:</b>						
Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:						
Corrective Action:					Date:	
<b>Paint</b>						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:	Containment berm damaged on the east end of the facility. It is not clear at time of inspection if BMP is in proper functioning condition. Maintenance advised.					
Corrective Action:				Date:		
<b>Venting:</b>						
Yes/No						
Comment:						
Corrective Action:				Date:		
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:				Date:		

**Inspected Facilities**

Facility ID: 490082 Type: LOCATION API Number: - Status: AC Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404340605	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7217282">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7217282</a>
718100772	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7217269">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7217269</a>