

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/03/2025

Submitted Date:

09/03/2025

Document Number:

719000569

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
 325619 \_\_\_\_\_ GARCIA, CHARLES \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: \_\_\_\_\_ 96735 \_\_\_\_\_  
 Name of Operator: WILLIFORD RESOURCES LLC \_\_\_\_\_  
 Address: 6506 S LEWIS AVE STE 102 \_\_\_\_\_  
 City: \_\_\_\_\_ TULSA \_\_\_\_\_ State: \_\_\_\_\_ OK \_\_\_\_\_ Zip: \_\_\_\_\_ 74136 \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 10 \_\_\_\_\_ Number of Comments
- 3 \_\_\_\_\_ Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name     | Phone | Email                       | Comment |
|------------------|-------|-----------------------------|---------|
| ,                |       | glennstevens95@gmail.com    |         |
| , GENERAL        |       | hwilli@swbell.net           |         |
| Labowskie, Steve |       | steve.labowskie@state.co.us |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 215114      | WELL | SI     | 01/01/2023  | OW         | 067-06719 | M & M 6       | SI          |

**General Comment:**

Inspection Report Summary  
 On 9/3/25 I Inspector Charles Garcia  
 conducted an on-site inspection.  
 Location: M&M 6  
 Operator: WILLIFORD RESOURCES  
 API#: 067-06719  
 County: LaPlata

**Location**

Overall Good:

| <b>Signs/Marker:</b> |                      |       |  |
|----------------------|----------------------|-------|--|
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             | CRUDE OIL TANK       |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             | LOCATION SIGN        |       |  |
| Corrective Action:   |                      | Date: |  |

|                           |                               |       |  |
|---------------------------|-------------------------------|-------|--|
| Emergency Contact Number: |                               |       |  |
| Comment:                  | 918-712-8828<br>911 EMERGENCY |       |  |
| Corrective Action:        |                               | Date: |  |

| <b>Good Housekeeping:</b> |  |       |            |
|---------------------------|--|-------|------------|
| Type                      | UNUSED EQUIPMENT                                   |       |            |
| Comment:                  | UNUSED EQUIPMENT ON LOCATION SEE LOCATION PICTURES |       |            |
| Corrective Action:        | Unnecessary equipment COMLPY WITH RULE 606         | Date: | 11/03/2025 |

Overall Good:

| <b>Spills:</b>   |      |        |  |
|--|------|--------|--|
| Type   | Area | Volume |  |
| In Containment: No                                     |      |        |  |
| Comment:   |      |        |  |
| <input type="checkbox"/> Multiple Spills and Releases? |      |        |  |

| <b>Fencing/:</b>   |               |       |  |
|--------------------|---------------|-------|--|
| Type               | PUMP JACK     |       |  |
| Comment:           | CATTLE PANELS |       |  |
| Corrective Action: |               | Date: |  |

| <b>Equipment:</b>  |           |       | corrective date |
|--------------------|-----------|-------|-----------------|
| Type: Pump Jack    | # 1       |       |                 |
| Comment:           |           |       |                 |
| Corrective Action: |           | Date: |                 |
| Type: Prime Mover  | # 1       |       |                 |
| Comment:           | GAS       |       |                 |
| Corrective Action: |           | Date: |                 |
| Type: Other        | # 1       |       |                 |
| Comment:           | WELL HEAD |       |                 |
| Corrective Action: |           | Date: |                 |
| Type: Bradenhead   | # 1       |       |                 |
| Comment:           |           |       |                 |
| Corrective Action: |           | Date: |                 |

| <b>Tanks and Berms:</b>   |            |                     |                     |             |                       |
|---|------------|---------------------|---------------------|-------------|-----------------------|
| Contents  | #          | Capacity            | Type                | Tank ID     | SE GPS                |
| CRUDE OIL   | 1          | 400 BBLs            | PBV STEEL           |             | 37.138000,-108.103200 |
| Comment: PAINT STARTING TO FADE IN SPOTS AND RUST SEE LOCATION PICTURES   |            |                     |                     |             |                       |
| Corrective Action: 600.b MAINTAIN TANK PAINT  |            |                     |                     |             | Date: 12/03/2025      |
| <b>Paint</b>  |            |                     |                     |             |                       |
| Condition   | Inadequate |                     |                     |             |                       |
| Other (Content)   |            |                     |                     |             |                       |
| Other (Capacity)  |            |                     |                     |             |                       |
| Other (Type)  |            |                     |                     |             |                       |
| <b>Berms</b>  |            |                     |                     |             |                       |
| Type  | Capacity   | Permeability (Wall) | Permeability (Base) | Maintenance |                       |
| Earth   | Inadequate | Walls Insufficient  | Base Sufficient     | Inadequate  |                       |
| Comment: EROSION affecting berm permeability at tank battery<br>PRAIRIE DOG BURROWS INSIDE CONTAINMENT<br>SEE LOCATION PICTURES |            |                     |                     |             |                       |
| Corrective Action: Maintain berms per rule 603.   |            |                     |                     |             | Date: 11/30/2025      |
| <b>Venting:</b>   |            |                     |                     |             |                       |
| Yes/No  | NO         |                     |                     |             |                       |
| Comment:  |            |                     |                     |             |                       |
| Corrective Action:  |            |                     |                     |             | Date:                 |
| <b>Flaring:</b>   |            |                     |                     |             |                       |
| Type  |            |                     |                     |             |                       |
| Comment:  |            |                     |                     |             |                       |
| Corrective Action:  |            |                     |                     |             | Date:                 |

**Inspected Facilities**

Facility ID: 215114 Type: WELL API Number: 067-06719 Status: SI Insp. Status: SI

**BradenHead**

Date of Last Brhd Test: 07/23/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 404340838    | INSPECTION SUBMITTED | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7217607">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7217607</a> |
| 719000571    | LOCATION PICTURES    | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7217598">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7217598</a> |