

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON I01 697

Location #: 335693



Photo # 6632 From entrance to location

Photo # 6633 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON I01 697

Location #: 335693



Photo # 6634 Location



Photo # 6635 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON I01 697

Location #: 335693



Photo # 6636 Location



Photo # 6637 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON I01 697

Location #: 335693



Photo # 6638 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 6639 PRV vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON I01 697

Location #: 335693



Photo # 6640 Rupture disc vent line does not comply with CECMC pressure safety device rules



Photo # 6641 Rupture disc vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON I01 697

Location #: 335693



Photo # 6642 Unmarked deadman



Photo # 6643 Same unmarked deadman

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON I01 697

Location #: 335693



Photo # 6644 Same unmarked deadman



Photo # 6645 Unused equipment

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON I01 697

Location #: 335693



Photo # 6646 CHEVRON 275-1 BH line tied into flowline/no FORM 4 SUNDRY & no check valve

Photo # 6647 CHEVRON 275-1 BH line tied into flowline/no FORM 4 SUNDRY & no check valve

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON I01 697

Location #: 335693



Photo # 6648 CHEVRON 275-1 BH line tied into flowline/no FORM 4 SUNDRY & no check valve



Photo # 6649 CHEVRON 275-1 well lacks required signage

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON I01 697

Location #: 335693



Photo # 6650 CHEVRON 275-1 well lacks required signage

Photo # 6651 CHEVRON 275-1 well lacks required signage

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON I01 697

Location #: 335693



Photo # 6652 Open ended piping near wellhead/wildlife hazard



Photo # 6653 Open ended piping near wellhead/wildlife hazard

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON I01 697

Location #: 335693



Photo # 6654 Sign at start of spur road to location has previous operators name

Photo # 6655 Wellhead sign has previous operators name

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON I01 697

Location #: 335693



Photo # 6656 Wellhead sign has previous operators name

Photo # 6657 Wellhead sign has previous operators name

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON I01 697

Location #: 335693




Photo # 6658 Tank label has previous operators name

Photo # 6659 Tank labels have previous operators name

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON I01 697

Location #: 335693




Photo # 6660 Tank labels have previous operators name

Photo # 6661 Battery sign has previous operators name

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON I01 697

Location #: 335693



Photo # 6662 Leg on metal stand for chemical tank appears to be starting to buckle



Photo # 6663 Leg on metal stand for chemical tank appears to be starting to buckle