

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/08/2025

Submitted Date:

09/10/2025

Document Number:

715202898

**FIELD INSPECTION FORM**

Loc ID 416295 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10699  
Name of Operator: OWN RESOURCES OPERATING LLC  
Address: 305 S RIDGE STREET #6279  
City: BRECKENRIDGE State: CO Zip: 80424

**Findings:**

13 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                        | Comment |
|--------------|-------|------------------------------|---------|
| Dolezal, Pat |       | pat.dolezal@ownresources.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name  | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 416298      | WELL | PR     | 07/09/2010  | GW         | 125-11792 | CANTRALL 02-03 | PR          |

**General Comment:**

[This is a field audit of the scout card, related documents and the location conducted by SE Compliance Specialist Brian Welsh](#)

**Location**

|                    |                           |       |  |
|--------------------|---------------------------|-------|--|
| <b>Lease Road:</b> |                           |       |  |
| Type               | Access                    |       |  |
| comment:           | Two track through pasture |       |  |
| Corrective Action: |                           | Date: |  |

Overall Good:

|                      |                           |       |  |
|----------------------|---------------------------|-------|--|
| <b>Signs/Marker:</b> |                           |       |  |
| Type                 | OTHER                     |       |  |
| Comment:             | Lease signs by meter shed |       |  |
| Corrective Action:   |                           | Date: |  |
| Type                 | WELLHEAD                  |       |  |
| Comment:             | Lease sign by unit        |       |  |
| Corrective Action:   |                           | Date: |  |

Emergency Contact Number:

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

Overall Good:

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

Multiple Spills and Releases?

|                    |   |       |  |
|--------------------|---|-------|--|
| <b>Fencing/:</b>   |   |       |  |
| Type               | OTHER   |       |  |
| Comment:           | Metal panels around meter shed, VGS and pig station |       |  |
| Corrective Action: |   | Date: |  |
| Type               | PUMP JACK   |       |  |
| Comment:           | Metal panels around unit and wellhead               |       |  |
| Corrective Action: |   | Date: |  |

|                           |   |       |                 |
|---------------------------|---|-------|-----------------|
| <b>Equipment:</b>         |   |       | corrective date |
| Type: Gas Meter Run       | # 2   |       |                 |
| Comment:                  | Shared meter run for Cantrall 2-03 & 2-02 1.11 miles NW of wellhead |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Prime Mover         | # 1   |       |                 |
| Comment:                  | Electric motor  |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Ancillary equipment | # 2   |       |                 |
| Comment:                  | Electric panel and telemetry equipment at meter shed                |       |                 |
| Corrective Action:        |   | Date: |                 |

|                          |  |       |  |
|--------------------------|--|-------|--|
| Type: Vertical Separator | # 2  |       |  |
| Comment:                 | 2-Vertical gas separators 50% buried by meter shed |       |  |
| Corrective Action:       |  | Date: |  |
| Type: Pump Jack          | # 1  |       |  |
| Comment:                 | Jensen unit  |       |  |
| Corrective Action:       |  | Date: |  |
| Type: Pig Station        | # 1  |       |  |
| Comment:                 | Launching station on north side of meter shed      |       |  |
| Corrective Action:       |  | Date: |  |

**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 416298 Type: WELL API Number: 125-11792 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Casing production. Central meter run for \(Cantrall 2-2 & 2-3\) 1.11 miles NNW @ 39.93401/-102.27964. Production reports are up to date at time of inspection](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Compaction              | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description  | URL   |
|--------------|--------------|---|
| 715202927    | pumping unit | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7227067">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7227067</a> |