

Inspection Photos
Location Name: State 14-32
Location ID: 320756



Pic 1 wellhead / pumpjack

Pic 2 wellhead sign

Inspection Photos
Location Name: State 14-32
Location ID: 320756



Pic 3 tanks

Pic 4 Separators, ECD


Inspection Photos
Location Name: State 14-32
Location ID: 320756



Pic 5 Venting / flaring fumes are visible on ground as shadow

Pic 6 GMR on location is connected from Separator, to ECD's on location

Inspection Photos
Location Name: State 14-32
Location ID: 320756



Pic 7 GMR calibration card

Pic 8 back of card

Inspection Photos
Location Name: State 14-32
Location ID: 320756



Pic 9 glass with flame inside of ECD

Pic 10 Glass with flame inside ECD

Inspection Photos
Location Name: State 14-32
Location ID: 320756



Pic 11 middle ECD on location does not have flame inside of ECD

Pic 12 Open excavation on location

Inspection Photos
Location Name: State 14-32
Location ID: 320756



Pic 13 Open excavation

Pic 14 Water tank and Pit

Inspection Photos
Location Name: State 14-32
Location ID: 320756



Pic 15 Pit

Pic 16 Pit bird cover

Inspection Photos
Location Name: State 14-32
Location ID: 320756