

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/11/2025

Submitted Date:

09/11/2025

Document Number:

719000645

FIELD INSPECTION FORM

Loc ID 333708 Inspector Name: GARCIA, CHARLES On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Findings:

- 15 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260805	WELL	PR	11/01/2023	CBM	067-08511	STATE CD 2	PR
295649	WELL	PR	05/01/2025	CBM	067-09542	STATE CD 4	PR

General Comment:

[Inspection Report Summary](#)
On 9/11/25 | Inspector Charles Garcia conducted an on-site inspection.
Location: STATE CD 2 , 4
Operator: Simcoe LLC
API#: 067-08511, 067-09542
County: LaPlata

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	PRODUCED WATER TANK "Sign not legible		
Corrective Action:	PLACARD NEEDS TO BE REPLACED PER RULE 605 SEE LOCATION PICTURES		Date: 10/11/2025
Type	OTHER		
Comment:	LOCATION SIGN AT ENTERANCE		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	24 Hr #970-247-6916 Emergency #911		Date:
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	PRODUCED WATER TANK CATTLE PANELS		
Corrective Action:			Date:
Type	OTHER		
Comment:	METER HOUSE CATTLE PANELS		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	CATTLE PANELS		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	CATTLE PANELS		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	CATTLE PANELS		
Corrective Action:			Date:

Equipment:			corrective date
Type: Bradenhead	# 2		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		

Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 2		
Comment:	ELECTRIC		
Corrective Action:			Date:
Type: Pump Jack	# 2		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	METER HOUSE CALIBRATION IN COMPLIANCE		
Corrective Action:			Date:
Type: Ancillary equipment	# 6		
Comment:	ELECTRIC PANELS TELEMETRY EQUIPMENT		
Corrective Action:			Date:
Type: Other	# 2		
Comment:	WELL HEADS		
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 2		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		37.188400,-107.637800
Comment:	95 BBL PRODUCED WATER TANK				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:		
Corrective Action:		Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 260805 Type: WELL API Number: 067-08511 Status: PR Insp. Status: PR

Producing Well

Comment:		
Corrective Action:		Date:

BradenHead

Date of Last Brhd Test: 08/27/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 295649 Type: WELL API Number: 067-09542 Status: PR Insp. Status: PR

Producing Well

Comment:		
Corrective Action:		Date:

BradenHead

Date of Last Brhd Test: 08/27/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000654	LOCATION PICTURES	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7229517