

WELL NAME: MONTOYA 11-1 V & R, API #: 071-08141, INSP. # 716301519




PHOTO 1: WELL SIGN



**PHOTO 2: LOCATION.**

**COLORADO**  
Energy & Carbon Management  
Department of Natural Resources

## Calibration Report

Report Date: **7/29/24 8:48 AM**

Section 1 - Meter  
 Device ID: **108108141**  
 Location: **Montoya 11-1 V**

Section 2 - Setup

Current Plate Size	0.5
Plate Size	3.068
mos. Pressure	10.98
Pressure Base	14.73

Tap Type  
 SP Tap Location  
 Temperature Bias  
 Temperature Base

Flange	0
Up Str	60


Network: Sep 12, 2025 at 12:38:41 PM MDT  
 Local: Sep 12, 2025 at 12:38:41 PM MDT  
 +37.205001, -104.953551  
 Las Animas County  
 Altitude: 2516.7 meter  
 Speed: 2.7 km/h

Plate Inspected?	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	Dirty	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
Edges Sharp?	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	Plate Mic'd	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
Ring Damaged?	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	Pitted	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>

Section 3 - Meter Tube Inspection

Nicked?	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
---------	------------------------------	--

**PHOTO 3: Meter not calibrated annually ON V WELL. Calibrate gas metering equipment annually to comply with rule 430.d.(1). CA DATE 10-12-2025.**



**PHOTO 4: Meter not calibrated annually ON R WELL. Calibrate gas metering equipment annually to comply with rule 430.d.(1). CA DATE 10-12-2025.**



**PHOTO 5: FENCE IS IN DISREPAIR ON V WELL PIT. REPAIR FENCE AROUND PIT PER RULE 1002. CA DATE 10-12-2025.**



**PHOTO 6: FENCE IS IN DISREPAIR ON R WELL PIT. REPAIR FENCE AROUND PIT PER RULE 1002. CA DATE 10-12-2025.**